

From: [REDACTED]
To: [Norfolk Boreas](#)
Subject: Vattenfall - Boreas - Representation
Date: 14 September 2019 09:49:26

I would like to ask the Planning Inspectorate what Vattenfall are going to be doing to prevent the emissions of the 'worst greenhouse gas' there is (as announced by the BBC yesterday 13th September 2019), when their huge new projects are built (although hopefully, they will never be built without this safeguard)? With the huge size of substations coming to Necton, we will undoubtedly get huge quantities of SF6 as well! It surely can't be allowed so close to Colin King's family (425 metres)

<https://www.telegraph.co.uk/news/2019/09/13/worlds-powerful-greenhouse-gas-rise-due-green-energy-boom/> "Emissions of the gas in the UK and the rest of the EU in 2017 were the equivalent of putting an extra 1.3million cars on the road. As renewable projects are getting bigger and bigger, we have had to use it within wind turbines specifically," Costa Pirgousis, an engineer with Scottish Power Renewables, told the BBC. As we are putting in more and more turbines, we need more and more switchgear and, as a result, more SF6 is being introduced into big turbines off shore.

https://energypost.eu/why-the-eu-should-ban-sf6/?fbclid=IwAR30EgPuIfpO9XUtpMqOYK4ba4rRmruGJkBXY8tVgsNPfG_1kqquU6GN1sw
"SF₆ is the most potent greenhouse gas in existence and for this reason was included in the Kyoto Protocol's list of substances of which the use and emission should be minimized. Consequently, SF₆ has been banned for all applications in which alternatives exist. However, an exception has been made for HV and MV switchgear in the electrical industry.

https://www.bbc.co.uk/news/science-environment-49567197?fbclid=IwAR31-htcvvio0VwTBSx4WyoKUAQNp5e4IHc2lBc4gb9wVk4C_oL-18SFyA

"But leaks of the little-known gas in the UK and the rest of the EU in 2017 were the equivalent of putting an extra 1.3 million cars on the road. Levels are rising as an unintended consequence of the green energy boom. Across the entire UK network of power lines and substations, there are around one million kilograms of SF6 installed."



Virus-free. www.avg.com

From: [REDACTED]
To: [Norfolk Boreas](#)
Subject: Requested Material NECTON PLANE CRASH
Date: 20 November 2019 09:15:56
Attachments: [Report-converted.pdf](#)

Dear Sirs,

I apologise for not attending the recent OFH, but as Councillor Spain explained I have been made unwell by my efforts in the Vanguard procedures.

I will however be able to attend the OFH you have mentioned as possibly being held in Dereham/Swaffham area next April 2020, and am hereby requesting such a Hearing as you have asked people to do.

It will be of great help to local people, as many cannot take whole days off work to travel to Norwich/and or have no means of transport to Norwich, so thank you for the offer of coming to us.

REQUESTED INFORMATION

Listening to the recording of the recent OFH, I note that you asked for the person who discovered it to send you the details of the RDAF jet crash in Necton on the site proposed for Vanguard and Boreas.

I am that person so I am sending the information.

I had already sent the basic report through the Necton Substation Action Group's email, but will resend here as it appears you want it from me.

Please Note: I can see that the developer appears to have eliminated the plane crash and possible contamination from Boreas' application. That is not correct. The crash 'cone' went in the direction of Boreas from Vanguard, so is equally likely to be affected.

Severe conditions relating to possible contamination were imposed on the Vanguard development by the Environment Agency and Breckland Council, involving this site. I feel very strongly that Boreas needs to have at least the same requirements, because although the developer might say they will have already done them for Vanguard, they will not have if Vanguard is refused and Boreas becomes a stand alone project. I heard on the recordings that VF solicitor, Mr Houghton, said that Boreas should be considered as a stand alone project. Therefore the project must also be made to adhere to the conditions imposed on Vanguard.

If you are not able to access the Vanguard documents I can, if you wish send you a copy of those conditions imposed on Vanguard.

I have attached the actual report to this email. The actual documents however, I know from previous experience, are too numerous to send to you all at once through email as your mailbox has a limit on it.

Therefore the documents have to be sent in batches, and it is very helpful if the receipt of each one could be acknowledged so that I will know you got them all. So I will commence sending them as soon as I get your instructions to do so. In the meantime, the report as I say, is attached.

I await your instructions.

Regards

Jenny Smedley

Introduction

RDAF F-16(B) crashed near Necton on 11th December 1996, impacting between Ivy Todd Road and Necton Wood, the debris **covering 3 fields**. It is directly on the area Vattenfall plan to build 2 x 18.5 acre substations and dig a deep cable corridor.

Vattenfall failed to mention the crash and contamination on its Environmental Report despite being told about it on 5th June 2018 by Norfolk County Council and before that by local people.

Co-ordinates of impact: 52°39'29''N 00°47'83''E Approximately 16 km east of RAF Marham on a W to E trajectory. (doc M).

Contaminants mentioned in documents as listed throughout this report.

Radioactive substance (Doc G) warned of by IPC (an ex MOD department within the RAF according to the Environmental Agency – see doc P) – has been used in F-16s and their ammunition. Two missiles (of a possible 6) and 200 shells (of a possible larger number) were recovered. Depleted Uranium is also commonly used as counter-weights in aircraft both military and commercial.

Hydrazine (doc A)

Oil (doc A)

Aviation Fuel (doc A)

Composites, such as Carbon Fibre (doc A)

There is one document still being withheld by the RDAF. **As radioactive substance clearing is not reported in the redacted clean-up documents so far given, we have to ask if this is why the RDAF report is being withheld.**

F-16 crash site was recovered in 1996/1997 with a view to restoring it for **arable use only**, and only within the constraints of the knowledge available at the time. The clearance was not adequate either for **large scale development** or to comply with current standards and knowledge.

The **worst case scenario must be adopted** – which is that **contaminants may remain in the soil at a deep level**, and any disturbance could create an **environmental disaster**, especially with regard to water supplies. Vattenfall's onshore infrastructure will also entail the use of pile-driving. The vibration from this invasive procedure could disturb contaminated ground at depth, and from there contaminate water supplies.

With the complexity and spasmodic nature of the task, carried out in extreme weather, with documented anomalies to the prescribed procedures, lack of data (at that time) on the long term breakdown of hazards in plane crash sites of this type, which necessitated further monitoring for just arable use, the lack of wreckage recovered, the sensitivity of information still being withheld, and the importance of public credibility of the whole operation, it would be prudent not to disturb the crash site. We therefore urge the Planning Inspectorate to refuse Planning Consent on the site proposed, as it is **not a suitable site**. It is **disingenuous of Vattenfall to have ignored the plane crash and contamination** in their Environmental Impact Report.

The full report compiled by the RDAF **which is still withheld** was apparently supplied to the MOD with an expectation of confidentiality. It was subjected to a

Public Interest Test, and was adjudged 'The PIT found that the public interest in maintaining the confidence of the Royal Danish Air Force (RDAF) outweighed the interest in releasing documentation, held by the Ministry of Defence, which originated with the RDAF' (See doc L)

Details of clearance and demonstrations of it being inadequate to accommodate large scale development of the site

- Impact Crater, referred to in documents variously as being both 9m x 19m x **2m deep** and spread over 3 fields, (doc A) **and 30 feet deep** (doc L)
- The aircraft carried 6000lbs of fuel (doc A)
- The aircraft broke under such intense force that only a few pieces of wreckage were longer than 50cms. (doc A). Surely an impact of that force would create a crater more than 2m deep.
- Debris said to cover 1 square mile (doc B)
- Parts of aircraft recovered are mentioned as being a wing, the engine and jet pipe, the hydrazine tank, which had split open leaving several deposits, 2 acquisition missiles and 200 rounds of 20mm ball ammunition. (doc D)
- The ARO said he, 'was of the opinion that the body of the aircraft was buried in the bottom of the crater.' (doc E) but no mention is made of finding the body of the aircraft. The ARO also advised digging 50cm deep trenches outside the 5m contaminated area around the crater before wreckage recovery commenced. This would limit deep excavations for recovery of the plane to the area enclosed by these trenches. If one takes even the smallest reported crater size version of 19mx9mx2m deep, this equates to 547 tons of soil being moved in a fraction of a second, so the amount of energy released by such an impact could reasonably be expected to push wreckage beyond the 5m trench-imposed limit. If the 30 feet deep crater mentioned in the original reports is correct, the tons of soil moved and the possible spread of wreckage would be very much greater. **This would explain why such a small amount of the aircraft was reported as being found, as excavations outside the trenches would not have been deep enough to locate it.**
- Contaminated soil was **mistakenly added to the clean soil pile** by members of the clean-up crew. (doc E)
- In addition to this, a blizzard obliterated the site on 31st December 1996, which kept the clean-up crew away from the site. (doc D). When the clean-up crew returned to the site on 7th January, they found that **the contaminated soil had been transferred to a hard standing by persons unknown.** (doc E). This moving around of the soil (at least 4/6 times) may have enabled carbon fibres to have been spread all around the area. In time it would have become untraceable (as it bonds to soil) and is likely to still exist under and in the soil all around the area.
- This is confirmed by the monitoring strategy which was advised for the whole site, for any further environmental impact, including the possibility of carbon fibres entering the food chain. It was admitted that at the time **no data was available on the long term breakdown of carbon composite fibres from aircraft crashes.** And that an area of approximately 1200m² was contaminated carbon fibres to **varying depths.** (doc E) There are no available reports on any on-going assessments and it is unknown if they were carried out.

- Further, the PHMDiv were asked to continue monitoring for ‘**re-emergence**’ of **carbon fibre**. (doc E) There is no information on whether this monitoring for environmental damage ever took place. The word ‘re-emergence’ implies that **contamination was indeed suspected at levels lower than what was examined**.
- Consultations with the Environment Agency and a subsequent ground water vulnerability survey, confirmed that the aircraft crashed in the vicinity of a major chalk aquifer used for the abstraction of private and public water supplies. The aquifer is covered with a 20m layer of boulder clay and flint. The soil structure has a moderate ability to attenuate diffuse source pollutants, but liquid discharges could penetrate this soil layer. The local Environment Agency officer expressed the opinion that there was little risk to either the aquifer or the nearby stream. (doc E). **However this did not take into account what might happen if a future deep excavation disturbed the soil again**.
- Tile drains over all 3 fields were wrongly identified by the clean-up crew as being mole drains. This showed an unfortunate lack of expertise in arable matters. (doc E)
- **The danger to health from burnt carbon fibre was underestimated by modern standards**, limited only to mentions of the possibility of needlestick injury. (doc E) Carbon Fibre is harmless in normal use but if exposed to high impact and high heat at the same time, this causes the polymer to melt away and the fibres (which can be inhaled and also penetrate skin) to float free, also bonding to soil.
- **Modern thinking on carbon fibres** <https://www.ed.ac.uk/inflammation-research/news-events/2017/carbon-nanotubes-may-pose-cancer-risk>
- The landowner was told that he could not grow any crops on the main field for a **minimum of 1 year**. (Necton Parish Council Meeting March 1997 – doc N). It was also been stated by a Parish Councillor, Ms Jean Bass (doc J) ‘They said the land was contaminated **for 5/7 years. Any residential growth would need special clearance.**’ Whilst Vattenfall’s project does not involve residential growth, it would have been unimaginable in 1996/1997 that a massive industrial project like this would ever be allowed to be built on arable land, and this could be why it was not specified in the instructions. The Air Control Report that is still withheld by the RDAF/RAF/MOD might clarify the above.
- The F16 is said by the RDAF to have impacted at the crash site on a W to E trajectory. However the main orientation of the area of search appears to lay in a N to S direction from the impact point. Burning debris fell to the ground at Ivy Todd Farm, (doc I) which does not lay within the area of search, but is some distance further to the East, and was not visited by clean-up crew, which would suggest that some **contamination remained undiscovered**. It would therefore appear that the splatter cone may have been wrongly placed. This is borne out by the fact that the only parts mentioned as having been recovered are as previously listed, so **large parts of the F16 may remain undiscovered**.
- One document speaks of ‘defensive press lines, which have been redacted. We would like to know what they were defending. (doc F).
- Monitoring – the latest information from the MOD – (document Q) states that although continued monitoring of the site (after January 1996) was required, there is no evidence that it was ever carried out.

CONCLUSION:

1. The cost of remediating contaminated ground over such a wide area could be so significant that it **should not be ignored in the estimated project costs, which is currently the case**, as it has not been mentioned in any way by Vattenfall in their DCO Application.
2. The population of Necton and Ivy Todd feel strongly that this site should not be disturbed as **no-one can guarantee that no harm will result from it**. There are very few sites in Norfolk that have had a modern jet crash into them with the possible environmental hazards of this one, and yet Vattenfall have indeed chosen one out of the many other options offered. It shows a lack of competence in their environmental investigations, and they **should be made to seek a different site that doesn't hold such potential damage to the area**.
3. CPO requirements appear to state that it must be proven that there was not another, better site other than the one chosen, which might have been purchased voluntarily. There are many viable sites that do not have the remains of an F16 air crash on them and would therefore be immeasurably better. **Vattenfall were for instance offered Top Farm in Necton, which stands on lower ground, would be easier to mitigate, and has 186 clean acres of land. This is the farm across which VF are currently planning to build their access road to their chosen site. Top Farm is on the current cable route from the coast and also has direct access to the A47.**
4. We would also ask what information **the RDAF are concealing** in the Air Crash Report we are not allowed to see.
5. It is clear that there were many problems in the clearing of this site, which in modern times would make the clearance inadequate. The clearance may have been acceptable at the time for restoration of the site to arable use, but certainly it would **not be considered sufficient either then or today for a major development**. And it would appear that the required monitoring of the site was not carried out, so no-one is able to state with certainty that the site is clear of contamination.
6. The complications and lack of knowledge of the time, and imprecise boundaries means that it would be extremely difficult to go back and make a 100% guaranteed clearance check

If there are any doubts at all, development should not be permitted on this site.

Additional Information.

<http://webarchive.nationalarchives.gov.uk/20081013111454/http://www.mod.uk/DefenceInter.net/AboutDefence/CorporatePublications/HealthandSafetyPublications/Uranium/>
<https://www.gov.uk/guidance/depleted-uranium-du-general-information-and-toxicology#what-is-depleted-uranium-du>

List of documents

- A – Factual Information Regarding the Crash of a Danish F-16
- B – Enclosure 2- Danish Air Force F16 Accident on Departure from RAF Marham
- C – Enclosure 5- Update on Danish Air Force F16 Accident
- D – Enclosure 12- Report on the Recovery of an RDAF F-16 Trainer
- E – RAF Institute of Health and Medical Training Report IHMT/5/97
- F – Loose Minute – RDAF-F16-ACCIDENT-11DEC86
- G – Land contamination crash 2
- H – Land contamination air crash
- I - statement by Mr Colin King, owner of Ivy Todd farm

J – Jean Bass email
K – F01201806031 covering letter
L – F01201811881 covering letter
M – RAF Map enlarged site of crash
N – Extract from Necton Parish Council Meeting March 1997
P – Email from Environment Agency regarding the identity of the IPC
Q – Document from MOD stating no monitoring on record.

Authors of this report: Alice Spain, Colin King, Tony Smedley, Jenny Smedley

From: [REDACTED]
To: [Norfolk Boreas](#)
Cc: [Norfolk Boreas](#)
Subject: Requested Material NECTON PLANE CRASH Batch 1 of 3
Date: 21 November 2019 07:59:35
Attachments: [A - Summary from RDAF.pdf](#)
[B- Enclosure 2.pdf](#)
[C- Enclosure 5.pdf](#)
[D- Enclosure 12.pdf](#)
[E- Env Health Rep F16 Norfolk.pdf](#)
[F- Loose Minute- RDAF-F16-ACCIDENT-11DEC86.pdf](#)

Dear Examining Authority

During OFH1 on 13th November Councillor Alice Spain was asked to have the attached documents sent to you by the person who acquired them.

I sent you the actual report asked for yesterday 20th November.

The documents to be attached to this report have to be sent in batches as your mail box cannot accept them all at once (I am told), so here is batch 1 of 3.

I would be most grateful if you could acknowledge receipt of all 3 so that I know they arrived safely.

Thank you

Jenny Smedley



Annex to Defence Command
Denmark File no: 2018/028377
Doc no: 1886742

DEFENCE COMMAND DENMARK AIR STAFF

Factual information regarding the crash of a Danish F-16 in December 1996 at Marham, Norfolk, UK.

The following facts are derived from the 1996 provisional report by the Danish MoD Commission on Accidents in Flight.

Coordinates of the crash site:

52°39'29"N 00°47'83"E Approximately 16 kilometers east of RAF Marham.

The impact created a crater approximately 9 x 19 meters and about 2 meters deep. The wreckage was spread over an area which consisted of a harvested field of mangolds, a field that had been ploughed in the autumn and a field sown with winter corn.

The accident spread carbon fiber, hydrazine, oil products and some 6,000 lbs of fuel. The concentration of hydrazine was neutralized using chlorine products.

The aircraft crashed into a field in an agricultural area. The aircraft's direction of movement at the moment of impact was 089 degrees. On impact with the ground the aircraft broke up and pieces of wreckage were spread over a fan-shaped area within an angle of +/- 80 degrees relative to the direction of movement and up to a distance of approximately 700 meters from the main impact point. The aircraft broke up into pieces with such force that only a few pieces of wreckage were longer than 50 centimeters.

STC/4511/1/8/FS

12 Dec 96

TO: STC DO

SUBJECT: DANISH AIR FORCE F16 ACCIDENT ON DEPARTURE FROM RAF
MARHAM - 11 DEC 96

1. A Royal Danish Air Force (RDAF) F16B crashed near the village of Necton, some 9 nm east of RAF Marham, at 0954Z today, 6 minutes after take-off from RAF Marham en-route to Vaerlose. The crew of 2 both ejected successfully and the aircraft came down in open farmland with no civilian casualties or collateral damage to property.

2. The F16, based at Skydstrup, arrived at Marham on 6 Dec 96 planning for an over-night stay which was extended due to weather. The F16 was serviced by Danish groundcrew who were required once the aircrew turn-round became invalid, after 24 hrs. Signs of fire were reported, by ATC, to be coming from the aircraft on take-off and as the pilot de-selected reheat he had a fire caution illuminate at which point the crew ejected. Engine blades have been recovered from the RW.

3. Following ejection, the crew landed in trees remote from the ac final crash site. The crew were taken to Kings Lynn hospital, by SAR helicopters from RAF Wattisham. [REDACTED]

Redacted Sect 44

4. RAF Marham assumed PCM responsibility and, in addition to the immediate crash services, despatched an Incident Officer (OC Eng & Supply), who made a heli-borne inspection of the crash site, and personnel to secure the site. The ac crash site is compact and the ejection seats and cockpit canopy have been recovered, at some distance from the main area of impact. Crash site hazards are hydrazine, MMMF and 200 rounds of 20mm ball ammunition.

5. An ARO [REDACTED] Redacted Sect 40- WO A was despatched from RAF St Athan, ETA 1700 hrs, and the AR&TF are alerted for wreckage recovery. RAF Coltishall, who have PCM responsibility for Norfolk, will assume PCM responsibilities at 1200 hrs on 12 Dec 96. ARO and AR&TF are on site. The main wreckage is in a deep crater in boggy ground, with debris over about one square mile. The provisional estimate is that the site will need to be guarded for about 14 days. Due to overseas detachments, Coltishall cannot maintain its guarding commitment, 60 personnel, past Sunday 15 Dec. CMLO is attempting to arrange support from Marham, Neatishead and Honington in order to minimise disruption to personnel in the xmas period.

6. OC RAF Marham [REDACTED] Redacted Sect 40- Gp Capt G advised the base commander at Skydstrup of the accident and an F16 exchange pilot from RAF

ENCLOSURE
5

STC/4511/1/8/FS

PSO to AOCinC
PSO to COS
SO to SASO
SO to AO Eng & Supply
PSO to AOC 1 Gp
Air Cdre Ops
Gp Capt Supt & Trg
Gp Capt Air Ops

20 Dec 96

UPDATE ON DANISH AIR FORCE F16 ACCIDENT - 11 DEC 96

1. The Danish Board of Inquiry has now completed its preliminary report of the factual events of the accident. However, it is in Danish and a translation will not be available for several days.
2. The Danish and RAF wreckage recovery teams are still working to clear the site, they have already removed most of the wreckage from the area surrounding the primary impact point, but now have a painstaking task to clear the remaining debris from what is a large crater. Work is expected to continue till the end of the first week in the new year. The wreckage will be recovered to Denmark for thorough investigation.
3. By Saturday, 21 Dec, the RAF guard force will be reduced to a total of 16 personnel of all ranks due to the reduced spread of the wreckage. RAF Coltishall continue with the lead on Post Crash Management, but are being supported by RAF Marham, RAF Honington, RAF Cottesmore, RAF Coningsby and RAF Wittering who will all provide personnel over the Christmas period.

Redacted Sect 40- Sqn Ldr F

FS Eng
Ext 6360

RESTRICTED

Lakenheath is en-route to Marham to assume initial liaison. IFS advised the Danish Defence Attache and contacted the Danish FS authorities, who will form a national Safety Investigation Committee, IAW the appropriate STANAG 3531.

7. The 11 man team, under the chairmanship of a [Redacted Sect 40-], Lt Col D [Redacted], arrived at Marham by Hercules transport about 1800 hrs 11 Dec 96. The team has similar disciplines to an RAF board and includes a 5 man specialist wreckage site clearance team. The team are based at Marham and OC Ops Wg [Redacted Sect 40- Wg Cdr H] reports them to be capable and enthusiastic, having established good working relationships. An air reconnaissance by Wessex of the crash site was conducted 12 Dec 96. Testing for hydrazine has been completed and carbon fibre contamination has been found to be present on the site.

8. The nation where the accident occurred may, with the concurrence of both nations, attach an officer to the operating nation's investigation committee as an official assistant or observer and OC STANEVAL RAF Marham [Redacted Sect 40- Sqn Ldr I] has, with the concurrence of AOC 1 Gp, assumed this role. An IFS BOI advisor [Redacted Sect 40- Sn Ldr J] is available should he be required.

9. CPRO has actioned the PR aspects of the accident.

[Redacted]

Redacted Sect 40- Wg Cdr K

CFSO
ext 7638

RESTRICTED

RESTRICTED

of a [Redacted Sect 40- Lt Col D] The team is expected to arrive at Maxham by Hercules transport about 1800 hrs today.

7. The nation where the accident occurred may, with the concurrence of both nations, attach an officer to the operating nation's investigation committee as an official assistant or observer. IFS [Redacted Sect 40- Sqn Ldr L] has recommended the appointment of [Redacted Sect 40- Sqn Ldr M] currently OC Jim at RAF Coltishall but until recently an IFS BOI adviser. HQ 1 Gp have been advised of this requirement. and RAF Maxham OC STRAWER has been appointed

8. As an interim measure, [Redacted Sect 40- Sqn Ldr J] an IFS BOI Adviser, is available to assist OC Ops RAF Maxham [Redacted Sect 40- Wg Cdr H] with preparation for the investigation, should he require assistance, but IFS would not wish him to become the observer to the investigation.

9. CPRO has actioned the PR aspects of the accident.

10. RAF Maxham planned to receive the team about 1800 hrs

[Redacted Sect 40- Wg Cdr K]

CPSO
ext 7633

12 Dec 91
1. [Redacted Sect 40- Wg Cdr K] assumed full responsibility with a view to
for of a personal or duty assignment requiring a
commitment of the personnel for about the next 14 days
(over seas)
2. [Redacted Sect 40- Wg Cdr K] has detached into the middle east and
cannot maintain the guarding post as discussed
3. [Redacted Sect 40- Wg Cdr K] is attempting to put a package together for
station also to the accident site - Coltishall, Maxham,
Houghton, [Redacted Sect 40- Wg Cdr K] had to meet the [Redacted Sect 40- Wg Cdr K]

[Redacted Sect 40]

RESTRICTED



ROYAL AIR FORCE

St Athan Barry Vale of Glamorgan CF62 4WA

A Unit of the RAF Maintenance Group Defence Agency

Telephone PSTN Direct Dial-In 01446 7901446 798116

PSTN Operator 01446 798798

GPTN 95421 Ext 01446 798116

Fax 01446 798660



12i

56ct
MAR 5 1997

See Distribution

file ref: 140/7

Please reply to The Officer Commanding

Your reference

Our reference

SA/7932/Eng

Redacted Sect 40

24 January 1997

10 10/17

REPORT ON THE RECOVERY OF AN RDAF F-16 TRAINER ET 205 FROM MONA FARM, NECTON, SWAFFHAM, NORFOLK.

1. Enclosed is the report appertaining to the recovery of ET205 which crashed at Mona Farm, Necton, Norfolk on 11 Dec 96.
2. Recommendations are made for considerations of AMM2 and EIFS(RAF).

T10/2

Redacted Sect 40

[Redacted]

Redacted Section 40- WO A

for Officer Commanding

Enclosure

1. Report on the Recovery of F16 Falcon Trainer ET205.

ARCHIVES
NOT TO BE REMOVED

ROYAL AIR FORCE INSTITUTE OF HEALTH AND MEDICAL TRAINING



PUBLIC HEALTH MEDICINE DIVISION

A REPORT ON AN ENVIRONMENTAL ASSESSMENT OF THE CRASH
SITE OF A ROYAL DANISH AIR FORCE F16 FIGHTING FALCON DUAL
SEAT TRAINER NEAR NECTON, SWAFFHAM, WEST NORFOLK

Report No: IHMT/5/97

February 1997

**ROYAL AIR FORCE INSTITUTE OF HEALTH
AND MEDICAL TRAINING**

**A REPORT ON AN ENVIRONMENTAL ASSESSMENT OF
THE CRASH SITE OF A ROYAL DANISH AIR FORCE
F16 FIGHTING FALCON DUAL SEAT TRAINER
NEAR NECTON, SWAFFHAM, WEST NORFOLK**

REPORT NO: IHMT/5/97

SUMMARY

1. On 11 December 1996, a Royal Danish Air Force F16 Fighting Falcon Dual Seat Trainer crashed in an arable field near Necton, Swaffham, West Norfolk. A team from the Public Health Medicine Division attended the site to assess the environmental impact of the crash and to advise on the necessary steps to minimise or eliminate any effect on the environment.
2. A considerable quantity of fuel and carbon composite fibre was spread over an area of approximately 1200m². In addition, hydrazine contamination had occurred as a result of damage to the aircraft's Emergency Power Unit.
3. Recommendations were made for the restoration of the crash site.

[REDACTED]
Flight Lieutenant
Officer Commanding
Environmental Protection
and Public Health

[REDACTED]
Wing Commander
Officer Commanding
Public Health Medicine Division

[REDACTED]
Wing Commander
Officer Commanding
Royal Air Force
Institute of Health
and Medical Training

12 February 1997

CONTENTS

	Page	Paras
INTRODUCTION	1	1-2
THE ASSESSMENTS		
FIRST ASSESSMENT	1	3-9
SECOND ASSESSMENT	3	10-14
FINAL ASSESSMENT	4	15-17
CONCLUSIONS	5	18
DEBRIEF	5	19
ADDENDUM	6	20
ANNEXES		
		Page
ANNEX A: Map showing the groundwater layout of the area surrounding the crash site		A-1 to A-2
ANNEX B: Plan of the crash site showing areas of fuel contamination		B-1
ANNEX C: Hydrocarbon Test Kit - Field Data Sheet		C-1

ROYAL AIR FORCE INSTITUTE OF HEALTH AND MEDICAL TRAINING

A REPORT ON AN ENVIRONMENTAL ASSESSMENT OF THE CRASH SITE OF A ROYAL DANISH AIR FORCE F16 FIGHTING FALCON DUAL SEAT TRAINER NEAR NECTON, SWAFFHAM, WEST NORFOLK

INTRODUCTION

1. On 11 December 1996, a Royal Danish Air Force (RDAF) F16 Fighting Falcon Dual Seat Trainer carrying approximately 6,000lb (3,375 litres) of fuel crashed into a ploughed field between Lodge Farm and Mona Farm near Necton in West Norfolk after taking off from RAF Marham. The aircraft produced a 3m deep crater and spread aircraft wreckage and aviation fuel over a wide area of the field. The crash site was also contaminated with hydrazine from the aircraft's Emergency Power Unit (EPU) and burnt carbon composite fibres.

2. In association with the Environmental Health Department (EHD) Duty Crash Response Officer (DCRO), a team from the Public Health Medicine Division (PHMDiv) of the RAF Institute of Health and Medical Training (IHMT) attended the crash site on 11-16 December 1996 to assess the environmental impact of the crash and to advise the Aircraft Recovery Officer (ARO) on the steps necessary to minimise or eliminate any adverse pollution effects. Further monitoring was carried out on 27-30 December 1997 during the excavation of the crash crater, and on 7 January 1997 for completion of the consignment notice prior to removal of soil contaminated with fuel.

THE ASSESSMENTS

FIRST ASSESSMENT - 11-16 DECEMBER 1996

3. Consultations with the Environment Agency and the local authority Environmental Health Officer, together with a subsequent ground water vulnerability survey, confirmed that the stricken aircraft had crashed in the vicinity of a major chalk aquifer used for the abstraction of private and public water supplies. The soil above this aquifer consists of a 20m layer of boulder clay and flint. The soil structure has a moderate ability to attenuate diffuse source pollutants, but liquid discharges could penetrate this soil layer. However, the local Environment Agency officer expressed the opinion that there was little risk to either the aquifer or the nearby stream. Annex A shows the groundwater layout of the area surrounding the crash site.

4. The main threat to personnel on the site and to the environment was from hydrazine liquid, a highly toxic rocket fuel used in the aircraft's EPU. The canister containing the hydrazine had split, resulting in several deposits within a 60 metre area down-slope from the crater. In order to alleviate this threat, the RDAF flew in a specialist hydrazine team. During the first 3 days of the crash recovery operations the RDAF team neutralised the hydrazine deposits using a 17% solution of calcium hyperchlorite. The soil in the immediate area of each deposit was then turned over so the clay soil beneath could deactivate the substance. All such deposits were marked with appropriate warning signs for the benefit of the aircraft recovery team.
5. During the period required by the RDAF to neutralise the hydrazine deposits, the team from the PHMDiv carried out visual and olfactory monitoring along the course of the adjoining stream. No specific evidence of pollution from the aviation fuel was found. However, there was a potential for contamination due to the sub-soil land drainage system (mole drainage) installed in the field. This system consists of a drain made in the soil by pulling a bullet-shaped device through the soil and adding clay pipes so that the compacted sides of the tunnel maintain that form for several years. These drains were located at a depth of approximately 1.5m, irrigating to the adjacent stream. Given the adverse weather conditions, any subsequent rainfall could have resulted in residual aviation fuel being flushed into the stream via the drainage system. To prevent such an occurrence a temporary boom was placed in the far corner of the field, downstream from the site.
6. Once the hydrazine team had completed their task, on-site analysis of the immediate area surrounding the crash site was carried out using a photo-ionising detector attached to a soil probe to monitor for hydrocarbon gases and vapours. Measurements were taken at one metre intervals to a depth of one metre, where possible, using a 30mm diameter Gouge Auger. Where high concentrations of fuel were detected, additional measurements were taken to establish both the extent of the contamination and the maximum depth. Additional measurements were also taken at the periphery of the crater to a distance of 5 metres. All the areas of fuel contamination were plotted and are graphically displayed at Annex B. These areas included the engine impact section and the location of one of the aircraft wings.

FINDINGS

7. The ARO was of the opinion that the body of the aircraft was buried in the bottom of the crater, which was 3 metres in depth. This was the area of heaviest contamination by aviation fuel. The area where the engine wreckage had landed was also heavily contaminated and the survey carried out by the team from PHMDiv showed that the soil immediately below this site was contaminated to a depth of 15cm. One of the wings had landed down-slope of the a pond near the crater, scattering fuel over a 720m² area to a varying depth of 2-5cm. In addition there was a light scattering of fuel in the area between the engine wreckage site and the main crater and another light scattering of fuel extended for approximately 30m north of the crater.

8. Deposits of burnt carbon fibre were found throughout the crash site area. The problem of carbon composite fibres was limited as superfine fibres would be dispersed from the area and, given the wet weather prevailing at the time, most of the remaining carbon composite fibre would be dampened down. However, larger pieces of carbon fibre could cause needlestick injury if not removed from the crash site.

RECOMMENDATIONS

9. The following recommendations were made following the first assessment of the crash site:

- a. Crops contaminated with carbon fibre composite are to be dampened down and removed, along with any contaminated soil, and incinerated, or disposed of as contaminated waste, to prevent them entering the food chain.
- b. Prior to their removal, it is recommended that all visible pieces of carbon fibre composite are dampened down to reduce the build up of composite dust particles.
- c. All fuel/oil collected in the bottom of the crater during the removal of the wreckage should be removed and disposed of by a competent contractor under the direction of the Defence Land Agency.
- d. All the areas of light fuel contamination between the engine wreckage site, the wing wreckage site and the main crater should be ploughed to turn the soil and then harrowed to increase the surface area of the soil, thereby allowing more oxygen into the soil and facilitating the evaporation of hydrocarbon vapours.

SECOND ASSESSMENT - 27-30 DECEMBER 1996

10. The aircraft carcass was due to be moved on 27 December, however, adverse weather conditions meant that no recovery work could be carried out that day. Nevertheless, the pollution monitoring team re-surveyed the crash site and the nearby stream for any possible extension of the fuel contamination.

11. The crash recovery team began removing the wreckage from within the contaminated area 5m around the crash crater on 29 Dec. On the advice of the DCRO, trenches were dug outside this 5m wide contaminated area to accommodate contaminated soil removed from the crater and the surrounding area during the wreckage recovery operations. The trenches were excavated to a depth of approximately 50cm. The soil in the trenches was beaten down to compact it and provide an impermeable layer. In addition the trenches were lined with plastic sheeting to prevent any contaminants leeching into the ground. The soil was sifted to locate any wreckage and any contaminated soil was then placed in the trenches. Soil which was deemed "clean" was placed in separate piles and labelled accordingly. Initially, there was some confusion regarding the crash recovery team's definition of "clean soil". The crash recovery team defined clean soil as that which was free of all

pieces of aircraft wreckage. Therefore, inadvertently, soil contaminated with hydrocarbons from the periphery of the crater was mixed with uncontaminated topsoil. When this became apparent all the soil heaps were re-sampled by the pollution monitoring team and the "clean" (uncontaminated) soil was identified and appropriately labelled.

FINDINGS

12. The contaminated soil which had been excavated from the crater and placed in the lined trenches was measured using a photo-ionising detector. Measurements recorded showed there was in excess of 200ppm of hydrocarbons from aviation fuel in the soil.

13. The soil removed from the periphery of the crater was found to be slightly contaminated, as first thought, but all signs of hydrocarbon contamination from aviation fuel were removed following exposure of the compact soil in the ground to the air.

RECOMMENDATIONS

14. The following recommendations were made following the second assessment of the crash site:

a. The contaminated soil placed in the trenches should be raked at the end of each working day to facilitate the introduction of oxygen into the soil and accelerate the evaporation of hydrocarbon vapours. Once all the wreckage and contaminated soil from the crater has been removed from the site, then this aerated soil could be returned to the periphery of the crater.

b. After the wreckage and soil have been removed from the crater the pollution monitoring team should quantify the amount of contamination and its constituents. This must be carried out prior to the removal of any contaminated soil from the site in order to comply with the Special Waste Regulations 1996. Contaminated soil must not be removed from a site **under any circumstances** until the consignment note has been completed with information of the levels of contaminant in the soil.

FINAL ASSESSMENT - 7 JANUARY 1997

15. The pollution monitoring team returned to the site on 7 January 1997 to quantify the amount of contamination in the soil that was to be removed for the consignment notice. It was observed that the contaminated soil which had originally been placed in the trenches had been transferred to a hard standing at the top-end of the field, where the farmer had stored straw. This soil was analysed using a "PetroFLAG" hydrocarbon test kit in order to quantify the level of contamination present from aviation fuel.

FINDINGS

16. After indicating the presence of fuel contamination using the photo-ionising detector, additional sampling using the "PetroFLAG" showed levels of contamination ranging from 99-265ppm, dependant on where the sample was taken from in the contaminated soil heap destined for removal(see Annex C).

RECOMMENDATIONS

17. The following recommendations were made following the final assessment of the crash site:

- a. The contaminated soil should be contained within the crash site area and should only be removed from the site by a competent waste contractor and disposed of in accordance with the statutory requirements of the Special Waste Regulations 1996.
- b. Arrangements should be made for the DCRO to return the crash site to take part in the handover of the field to the farmer and his agent once it has been cleared of all contamination.
- c. A monitoring strategy should be set up by a competent person, in consultation with the Defence Land Agency, to continue to assess the whole area for any further environmental impact, including the possibility of carbon fibres (if any) entering the food chain and the biodegradation of the aviation fuel on agricultural land. This recommendation is made because at present no data is available on the long term breakdown of carbon composite fibres from aircraft crashes in a natural environment.

CONCLUSIONS


18. The pollution problems associated with the F16 aircraft crash site were considerably widespread throughout the ploughed field. The potential problems associated with hydrazine contamination were dealt with by the team from the RDAF. With the exception of the aircraft crater and the engine wreckage site where there was heavy contamination, an area of approximately 1200m² was lightly contaminated by fuel and carbon composite fibres to varying depths.

DEBRIEF

19. The DCRO briefed the ARO on-site on the team's findings and the recommendations contained in this report. The ARO then briefed [REDACTED] of the Defence Land Agency. Ongoing briefings and updates took place between the DCRO, [REDACTED] of the Environment Agency, and [REDACTED] the local authority Environmental Health Officer.

ADDENDUM

20. Following the meeting between the DCRO, the Defence Land Agent, the farmer and the farmer's agent during the handover of the field, the pollution monitoring team from PHMDiv have been tasked to carry out further monitoring of the site of the F16 aircraft crash in the arable field for any adverse environmental effects and the re-emergence, if any, of carbon composite fibres.




Aircraft
Crash Site

VULNERABILITY CLASSES

Geological Classes

Soil Classes

Major Aquifer
(Highly Permeable)




High (H) 1, 2, 3, U*

Intermediate (I) 1, 2

Low

Minor Aquifer
(Variably Permeable)



High (H) 1, 2, 3, U*


Intermediate (I) 1, 2

Low

Non-Aquifer
(Negligibly Permeable)



Low permeability, non-water bearing drift deposits occurring at the surface and overlying Major and Minor Aquifers are head (clayey), shell marl, Nar Valley clay, Terrington Beds, Barroway Drove Beds, glacial silts and clays and till (excluding Cromer Till).



HYDROCARBON TEST KIT - FIELD DATA SHEET

Date: 7 Jan 97

Calibration Time/Date: 13:20 /7.1.97

Operator: XXXXXXXXXX

Calibration Temperature: 19° C

Location: F16 Crash Site Necton Nr Swaffham - Contaminated Soil Removal (Pile on hardstanding)

No	Sample ID	Weight	Time	Reading (ppm)	DF ¹	RF ²	Actual (ppm)	Comments
1	CS	10g	13:30	99	1	2	99	TOP
2	CS1	10g	13:32	149	1	2	149	TOP
3	CS2	10g	13:34	104	1	2	104	TOP
4	CS3	10g	13:36	114	1	2	114	EDGE
5	CS4	10g	13:38	136	1	2	136	EDGE
6	CS5	10g	13:40	141	1	2	141	EDGE
7	CS6	10g	13:42	101	1	2	101	EDGE
8	CS7	10g	13:44	106	1	2	106	EDGE
9	CS8	10g	13:46	265	1	2	265	CENTRE
10	CS9	10g	13:48	166	1	2	166	SUMMIT
11	Blank	-	13:28	00	1	2	00	-
12	Standard	-	13:29	1000	1	2	1000	-
13								
14								
15								
16								
17								
18								
19								
20								

Notes:

1. DF = Dilution Factor, eg for a 5 gram soil sample the DF = 10g/5g = 2, and actual concentration equals reading x DF (reading (ppm) x DF = actual concentration).

2. RF = Response Factor, selected for the hydrocarbon contamination at the site.

Distribution:

External:

Action:

HQLC Brampton (AMM2)
EIFS(RAF) - Rm 16 RAF Bently Priory

Information:

RAF Marham

Internal:

Action:

Information:

OC AESW
OC ASTS (on file)

REPORT ON THE RECOVERY OF AN RDAF F-16 TRAINER ET- 205 FROM MONA FARM, NECTON, SWAFFHAM, NORFOLK.

INTRODUCTION

1. On the morning of the 11 Dec the crew of a Royal Danish Air Force (RDAF) F-16 , ET 205, a student pilot and instructor, briefed for a return sortie from RAF Marham to their base in Denmark. After a routine start-up under the guidance of their own groundcrew, ET 205 took off at 0948 hrs. ATC reported to the crew that sparks were visible from the reheat flame as the aircraft rolled along the runway. After getting airborne the crew looked to the rear of their aircraft and saw flames reaching forward of the tailplane. The instructor pilot in the rear seat initiated command ejection, and the crew ejected successfully and came down safely in woods, just south of Narborough, some 2nm NE of RAF Marham. The aircraft continued on a random trajectory, climbing to 1200 ft, before descending and crashing on open farm land near the village of Necton, 10 nm E of RAF Marham.

RESPONSE

2. The Duty Aircraft Officer (ARO) was alerted by EIFS(RAF) at 1100 hrs and tasked to proceed to the crash scene and assist the RDAF investigators. The ARO and Site Co-ordinator left at 1200 hrs and on route made contact with both the Defence Land Agent (DLA) and the RAF Institute of Health and Medical Training (IHMT). Arriving during darkness at 1730 hrs, the ARO met and was fully briefed by the appointed Incident Commander (IC); OC Eng of RAF Marham. From this brief, it was quickly established that apart from the health and safety implications of hydrazine, aviation fuel and carbon composite fibres deposits, it should be a relatively straight forward recovery operation. The ARO then visited RAF Marham where he was introduced and briefed by OC Ops Wing, OC Eng HQ Flt, OC AEF and the RDAF Aircraft Investigators (AI). Having ascertained what had been said at both briefs, the ARO then informed AR&TF Control to the F16 recovery manpower and equipment requirements.

SITUATION/TOPOGRAPHY

3. Aircraft. The aircraft crashed on agricultural land owned by [Redacted Sect 40 Civ B] of Mona Farm. On impact, it produced a 3m deep crater and spread aircraft wreckage and aviation fuel over a wide area of what can only be described as a deeply harrowed and recently harvested sugar beet field. The crash site was also contaminated with hydrazine from the Emergency Power Unit (EPU) and burnt carbon composite fibres. The aircraft's ejection seats and canopy were located some 8 miles away in another recently ploughed field, with the parachutes being found close by, but stuck high up in 40ft trees.

CRASH SITE

4. The main wreckage area itself was gently sloping ground of some 100 acres and contained within its boundaries was a bush type copse, two small ponds and a field drainage river. A dirt track ran along three sides of the site and the Necton to Ivy Todd public road on the other. A safe and sensible cordon had been placed around the complete perimeter of the site which allowed uninterrupted use of the aforementioned road.

RECOVERY TEAM DEPLOYMENT

5. A recovery team of 9 including a qualified LSS wreckage plotter left St Athan, as directed through AR&TF Control by the ARO, at 1100 hrs on 12 Dec 96. They reported to the site at 0730 hrs on 13 Dec 96 and were tasked to set up the AR&TF control, support and accommodation facilities. By 1200 hrs on 13 Dec 96 the team were in position to respond to requests by the RDAF AI.

COMMAND AND CONTROL

6. In support of the F16 crash, RDAF had deployed a small party of personnel, which included a Board of Inquiry (BOI) president, aircraft investigators, hydrazine safety experts and a armament specialist. It was obvious by their limited number that this recovery would need AR&TF support in full. Therefore, after consultation with both EIFS and Danish BOI president, it was amicably agreed that the recovery of the F16 would be carried out under RDAF primacy, but iaw RAF Post Crash Management (PCM) procedures as contained in the AP100V-10.

7. The IC and the guard force were generated from RAF Marham; the nearest Unit to the crash site. They took control of the site from the onset and fully implemented the procedures and directives as laid down in the AP100V-10. This guarding commitment was later taken over by RAF Coltishall who maintained the excellent site control set by RAF Marham.

SURVEY AND RECOVERY

8. On the evening of 11 dec 96, [Redacted Sect 40- Maj C] OC AEF, RAF Marham, ARO and the RDAF armament specialist visited the site where the deployed ejection seats and canopy came to rest. Under a [Redacted Sect 40- Maj C] request the outline of the seats and canopy was painted on ground in order that their positions might be plotted in daylight on the next day. The seats were then disarmed and along with canopy were transported for safe keeping to RAF Marham. The parachutes and associated survival packs were retrieved from their lofty heights, again during daylight some 36 hrs later.

9. The initial survey of the main crash site was carried out on 12 Dec 96 by [Redacted Sect 40- Lt Col D] (BOI president), [Redacted Sect 40- Maj C] and the two RDAF hydrazine safety experts. They quickly located the aircraft's hydrazine tank, which had split open leaving several deposits within a 60 metre area down-slope from the crater. This area was deemed the inner cordon and only RDAF personnel were permitted to enter whilst the hydrazine threat was being alleviated by their specialist team. This lasted 3 days. During this time the RAF IHMT was advising the ARO on all health and safety measures to be employed, consulting with the local environmental agencies and carrying out an environmental assessment of the site. At the RDAF request a wreckage plot was commenced on the afternoon of 13 Dec 96. And, at the same time areas on the periphery of the outer cordon were being searched to ensure no parts had fallen from the aircraft prior to impact. The Defence Land Agent (DLA) arrived and began to contact the respective landowners. The Danish AI team, led by [Redacted Sect 40- Maj C] started to identify and remove vital parts of the wreckage from the inner cordon. At the request BOI president, AR&TF personnel found, plotted and removed the aircraft's engine and jet pipe which had landed in many different locations outside of the inner cordon. There were very few executive visits, if any, made to the main crash site or to the respective landowner during this early period of the recovery.

10. On the 14 Dec 96, a non flying window of opportunity allowed AR&TF and RAF Marham personnel to conduct a FOD sweep on either side of RAF Marham's main runway. This was mainly due to an eye witness report stating that pieces of red hot metal were seen coming from the F16's exhaust during its final take off. A sweep of the actual runway had been carried out shortly after the F16's last flight. Although these searches offered up some articles of interest, none were found to be F16 related.

RECOVERY OF MAIN SITE

11. The site was declared safe from the hydrazine on 15 Dec 96. On the same day, [REDACTED] left for Denmark. They were very polite and extremely generous in their praise of the AR&TF involvement. They left behind a liaison SNCO and a two man safety team for the duration of the recovery. The vital aircraft evidence that had been collected so far had been sent to RAF Marham for an onward and speedy dispatch to Denmark. The IHMT were on site accessing the carbon fibre hazard and advising the ARO on the dress category required. The recovery team, supplemented by spare personnel of the guard force were completing the sweep of the fields surrounding the crash site.

12. Recovery operations of the main site commenced in earnest on 16 Dec 96 and continued until 13 Jan 97. The progress was steady at first with the AR&TF team still being supplemented by six of the guard force. This was soon to change with overall guard force being slowly reduced and the threat of adverse weather. However, morale remained high and the non stop work continued up until the 24 Dec 96. The team was then stood down for 2 days. On the 28 Dec, the recovery team was split into two, one half continued to collect top surface wreckage whilst the other commenced excavation of the crater. A tracked excavator/digger and dumper truck were hired in support of the latter. Both operations were curtailed on 31 Dec 96 due to snow blizzards. The new year saw the complete site covered in snow, a situation where only excavation work was feasible. Except for two acquisition missiles, little wreckage was found in the crater. The RAF EOD team concurred this fact by checking the crater with their specialist detector equipment. On the 7 Jan 97 excavation of the crater was completed and the full team return to the field. The recovery operation continued till the 13 Jan 97. During this time both small ponds within the site were dredged for wreckage, none found. The main wreckage removed, stored in ISO containers and sent, via RAF Marham, to Denmark. The crater reclaimed, apart from the top soil level. And, finally in association with the DLA and IHMT, the ARO had all contaminated soil removed to licenced tips. The site was then handed over on 14 Jan 97 to the DLA for the completion of land recovery and compensation.

13. Environmental Health/Health and Safety at Work Aspects. The Hydrazine hazard gave concern throughout the recovery. However, the RDAF specialist team, dressed in chemical protective suits and full breathing apparatus, dealt with the initial contamination and there after, monitored the site through out the complete recovery. Both soil and water samples were taken by the IHMT team who were a necessary back up to the ARO. They briefed the DLA and the Landowner on their findings and full details can be found in their Report No: IHMT/5/97. Protective equipment was used, as directed by the ARO, by the AR&TF team and the support personnel of RAF Marham and Coltishall.

14. Team. An AR&TF recovery team of 10 carried out this task.

SUPPORT

15. RAF Marham gave every possible logistic and administrative support to the F16 recovery. Redacted Sect 40-
Sqn Ldr E OC Eng Wg HQ Flt of RAF Marham, was instrumental in this which set a fine example of inter unit co-operation.

RECOMMENDATIONS

16. This accident highlighted the dangers of hydrazine and the resultant need for specialist training, protective clothing and equipment; points that were made very clear by RDAF Hydrazine Safety Team during the recovery. This is an area that must be explored, sooner rather than latter, as we might not have the support of a specialist team the next time.

SUMMARY

17. This recovery operation was a splendid example of close cooperation between Units, different NATO Forces, Civilian Contractors and the Landowner(s). It gave a good insight into how the RDAF BOI and AI went about their work and how their safety team dealt with the hazards of Hydrazine. It was also very pleasing to receive the many compliments, from both RDAF and Redacted Sect 40-
Civ B the Landowner on the disciplined and professional attitude shown by the young men of AR&TF. Finally, as the ARO I could not have asked for better support from all the different agencies involved.



National Rivers Authority
Anglian Region

NRA

STATUS REPORT
STAT
STAT
STAT
STAT

STAT
FAX

ORT
ORT
ORT
ORT

FROM [REDACTED]
POST ACQO
LOCATION KINGS LYNN

TO REGIONAL COMMUNICATIONS CENTRE
FAX No. 01733 231944

FLOOD	POLL <input checked="" type="checkbox"/>	FIRST REPORT AND LAST	UPDATE	10:00 UPDATE	16:00	2 HRLY	AREA CONTROL ROOM			
							OPEN	CLOSED	TIME	DATE

HEADING AEROPLANE CRASH
LOCATION & TYPE OF INCIDENT WY TODD SWAFFHAM NORFOLK TIME & DATE 1730 11/12/96

F16 CRASHED AT NGR TF 894100. REPORT RECEIVED FROM NORFOLK FIRE & RESCUE AT 1030 HRS

INVESTIGATION REPORT

PLANE TOOK OFF FROM NARMAN (RAF) IN FLAMES, CREW EJECTED IMMEDIATELY. PLANE FLEW ON FOR APPROX 16 KM BEFORE CRASHING INTO SUGAR BEET FIELD. RECKAGE SPREAD OVER WIDE AREA (600m²). BIGGEST PART OF RECKAGE BURIED INTO GROUND MAKING LARGE HOLE. SIGNIFICANT STREAM 500m DOWNGRADIENT NOT AFFECTED. IE U/S OF POTABLE INTAKE AT STOKES FERRY (RIVER WISSEY). PLANE CARRYING HYDRAZINE. ANTICIPATE THAT ALL FUEL/CHEMICAL BURNT UP DURING FLIGHT & ON IMPACT. IFC HAVE INFORMED MAFF OF RADIOACTIVE SUBSTANCE RISK. NEAREST KNOWN POTABLE WELL/BOREHOLE 2KM. ENVIRONMENTAL HEALTH INVESTIGATING, OTHER LOCAL SUPPLIES. NO FURTHER ACTION FROM WATER QUALITY REQUIRED

DISTRIBUTION

R.C.C.	MAFF	AREA STAFF (name)			DISTRICT OFFICE (name)			OTHERS (name)			1 OF SHEETS
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	[REDACTED]			[REDACTED]						

TICK AS REQUIRED

OFFICER IN CHARGE [REDACTED]
OTHER ORGANISATIONS INVOLVED MAFF

COPIES

12-12-96

[REDACTED]

1020 MAFF

FAX MESSAGE


FAX DESTINATION NUMBER

COMPANY NAME

**ENVIRONMENT
AGENCY**

Anglian Region

FOR THE ATTENTION OF



SUBJECT MATTER

F16 Crash,



FROM



NUMBER OF SHEETS TO FOLLOW


0

Central Area Office
Bromholme Lane
Brampton
Huntingdon
Cams PE18 8NE
Tel: (01480) 414581
Fax: (01480) 413381

IF PART OF THIS MESSAGE IS MISSING OR ILLEGIBLE, PLEASE TELEPHONE

David,

I have contacted Ft, Lt, [redacted] at Marchon to tell him that there is approximately 0.4m soil over 20m of boulder clay before the Chert aquifer is reached. The aquifer is therefore reasonably protected. However, some shallow boreholes (7m - 15m) do have water in them at a level approx 5m below ground level, probably originating in higher permeability bands within the boulder clay. The nearest of these private abstractions is 800m to south but they shouldn't be affected if the Riel is removed quickly.






Ministry
of Defence

Air Historical Branch (RAF)
Bldg 824
RAF Northolt
West End Road
Ruislip
HA4 6NG
United Kingdom

Telephone [MOD]: +44 (0)20 8833 8175
Facsimile [MOD]: +44 (0)20 8833 8170
E-mail: Business ahb.raf@btconnect.com

Ref: FOI2018/06031

Ms J Smedley



29 May 2018

Dear Ms Smedley,

Thank you for your email of 2nd May 2018 requesting the following:

"I am trying to find out some information about contamination that was left behind after a Danish RAF jet crashed in a field close to my house in Necton, Norfolk PE37 8HY on 11th December 1996. Can you help me with this please or point me in the right direction?"

Local knowledge says that this is carbon fibre and/or depleted uranium from armaments."

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence, and we can confirm that some information in scope of your request is held.

The AHB (RAF) hold a copy of Loose Minute reference *D/Sec(AS)/58/1/36* dated 11 December 1996, which is attached. Some of the information falls entirely within the scope of the absolute exemption provided for at *Section 40 (2)* of the FOIA and has been redacted.

Section 40(2) has been applied in order to protect personal information as governed by the Data Protection Act 1998. As *Section 40 (2)* is an absolute exemption, there is therefore no requirement to consider the public interest in making a decision to withhold the information. The names and contact details of officials in the Senior Civil Service (SCS) and their military equivalents (Commodore, Brigadier, Air Commodore and above) are considered to be available in the public domain and have not been redacted.

AHB (RAF) also hold the RAF Marham RAF Form 540 (Operation Record Book) for the period which contains an entry in December 1996 as follows:

Statement by Mr Colin King, owner of Ivy Todd farm

On 11th December 1996 I was travelling to our outdoor pigs at the time of the plane crash, and heard the explosion, (sounded like two in quick succession) and saw the smoke, and blue flashing lights once I got out of the truck. When I got back to the farm, father explained how he heard bits landing on the pig building roof, (which he was in) with a phutting noise. He looked out, and saw what was like little burning candles coming down, and burning on the yard.

11 Dec AIR TRAFFIC CONTROL

Danish F-16 A Danish F-16 fighter aircraft crashed shortly after take-off from RAF Marham. The 2 man crew ejected shortly after take-off and the aircraft eventually crashed near the village of Necton, some 15km after the crew ejected. The aircraft fortunately came down in a field and there was no loss of life or damage to civil property apart from a large hole approximately 30 feet deep.

Under Section 16 of the Act (Advice and Assistance) you may find it helpful to note that the contact details for the Royal Danish Air Force are below:

Website:

<https://www2.forsvaret.dk/eng/Organisation/AirForce/Pages/RoyalDanishAirForce.aspx>

E-mail:

vfk@mil.dk

Address:

Defence Command Denmark,
Air Staff
Herningvej 30
DK-7470 Karup J.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <http://www.ico.org.uk>.

Yours sincerely,

Air Historical Branch (RAF)

RESTRICTED

LOOSE MINUTE

D/Sec(AS)/58/1/36

11 December 1996

PS/USofs*

* by CHOTS

copy to:

APS/Secretary of State*

APS/Minister(AF)*

APS/Minister(DP)*

PS/CAS*

PSO/ACAS

AUS(H&O)

Redacted - Sect. 40

Press Secretary*

Sec(AS)2*

HCDC Liaison Officer*

STC - CS(P&P)1

Chief Claims Officer*

Air Attache, Copenhagen

ROYAL DANISH AIR FORCE F-16 ACCIDENT - 11 DEC 96

1. I am writing to confirm the details of this morning's accident involving a two-seat F-16B aircraft of the Royal Danish Air Force (RDAF).
2. The aircraft arrived at RAF Marham on 5 December on a routine liaison visit but bad weather delayed the originally planned departure until this morning. Shortly after becoming airborne and with the aircraft in a steep climb, the crew encountered difficulties and ejected. The trajectory of the aircraft was such that it crashed in open farmland some seven miles away, just outside the village of Necton. The crew was picked up by a SAR helicopter and taken to King's Lynn Hospital having sustained only minor injuries. Early suggestions are that the accident may have been caused an engine failure.
3. Post-crash management personnel at the site are alert to the presence of a highly toxic, flammable chemical compound known as Hydrazine (H_4N_2) which the F-16 uses during the engine start-up sequence. Although only a small amount of the substance is carried, it can cause systemic poisoning and permanent kidney damage if improperly handled. RAF firecrews and personnel at the Aircraft Recovery & Transportation Flight are trained accordingly. In addition, RAF personnel detached to the scene immediately after the accident occurred took additional advice from United States Air Force personnel at RAF Lakenheath, who are more familiar with F-16 post crash management procedures.
4. NATO arrangements for investigating military aircraft accidents permit the authority owning the aircraft to investigate the crash if no other aircraft is involved. Accordingly, the RDAF will be investigating this accident and is setting up its own Board of Inquiry; a RAF observer will be in attendance.

RESTRICTED

RESTRICTED

5. I attach a draft letter for USofS to send to Gillian Shepherd, the MP in whose constituency the accident occurred. I do not believe that there is a requirement for the Department to advise the HCDC of this accident as although accidents to foreign aircraft were not specifically excluded from the reporting arrangements agreed earlier this year, the Committee's interest was focused on UK military aircraft losses and our inquiry procedures neither of which are, of course, relevant here. I also attach some defensive press lines.

Redacted - Sect. 40

RESTRICTED

DRAFT LETTER TO GILLIAN SHEPHERD MP

I am writing to confirm the details of the aircraft accident which occurred in your constituency this morning.

A two-seat F-16B aircraft of the Royal Danish Air Force had just taken off from RAF Marham, bound for Denmark, when the crew encountered difficulties and ejected. The aircraft crashed some four miles east of Swaffham. The crew were subsequently picked up by a RAF helicopter having sustained only minor injuries.

The investigation into this accident is being carried out by the Royal Danish Air Force under the terms of a NATO Standardization Agreement.

THE EARL HOWE

Rt Hon Gillian P Shepherd MP

PRESS LINES ON AIRCRAFT ACCIDENT INVOLVING A RDAF F-16B - SWAFFHAM
- 11 DEC 96

- Confirm that a two-seat F-16B of the Royal Danish Air Force has crashed seven miles east of RAF Marham.
- The aircraft had just departed Marham and was intending to return to Denmark when the crew encountered difficulties and ejected. They were subsequently picked up by SAR helicopter having sustained only minor injuries.
- The Royal Danish Air Force has convened a Board of Inquiry at which the RAF will have an observer.

If pressed:

- The aircraft was in a steep climb when the crew ejected and the trajectory of the aircraft was such that it continued to travel some distance before crashing into open farmland. It is entirely normal practice for F-16s to enter into a steep climb upon departure.

- It will be a matter for the Danish authorities whether they wish to make the findings of their Inquiry public.

- Confirm that F-16 aircraft carry a small amount of Hydrazine, which is used during the aircraft's start-up sequence. As with any chemical compound, Hydrazine is entirely safe provided it is handled only by trained and properly equipped professionals.

- We are not aware of any claims arising from this accident but any that we receive will be considered fairly and objectively.




Ministry
of Defence

Air Historical Branch (RAF)
Bldg 824
RAF Northolt
West End Road
Ruislip
HA4 6NG
United Kingdom

Telephone [MOD]: +44 (0)20 8833 8175
Facsimile [MOD]: +44 (0)20 8833 8170
E-mail: Business ahb.raf@btconnect.com

Ref: FOI2018/06031

Ms J Smedley



29 May 2018

Dear Ms Smedley,

Thank you for your email of 2nd May 2018 requesting the following:

"I am trying to find out some information about contamination that was left behind after a Danish RAF jet crashed in a field close to my house in Necton, Norfolk PE37 8HY on 11th December 1996. Can you help me with this please or point me in the right direction?"

Local knowledge says that this is carbon fibre and/or depleted uranium from armaments."

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence, and we can confirm that some information in scope of your request is held.

The AHB (RAF) hold a copy of Loose Minute reference *D/Sec(AS)/58/1/36* dated 11 December 1996, which is attached. Some of the information falls entirely within the scope of the absolute exemption provided for at *Section 40 (2)* of the FOIA and has been redacted.

Section 40(2) has been applied in order to protect personal information as governed by the Data Protection Act 1998. As *Section 40 (2)* is an absolute exemption, there is therefore no requirement to consider the public interest in making a decision to withhold the information. The names and contact details of officials in the Senior Civil Service (SCS) and their military equivalents (Commodore, Brigadier, Air Commodore and above) are considered to be available in the public domain and have not been redacted.

AHB (RAF) also hold the RAF Marham RAF Form 540 (Operation Record Book) for the period which contains an entry in December 1996 as follows:



Ministry
of Defence

Air Historical Branch (RAF)
Bldg 824
RAF Northolt
West End Road
Ruislip
HA4 6NG
United Kingdom

Telephone [MOD]: +44 (0)20 8833 8175
Facsimile [MOD]: +44 (0)20 8833 8170
E-mail: Business ahb.raf@btconnect.com

Ref: FOI2018/11881

Ms J Smedley

[REDACTED]

21 September 2018

Dear Ms Smedley,

Thank you for your email of 18th September 2018 requesting the following:

"Does the MOD have any information as to how long the farmer was advised to keep off the land, and the item recalled by our Parish Council, which stated that a major development on the land needed special permission."

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence, and we can confirm that some information in scope of your request is held. Attachment E- RAF Institute of Health and Medical Training Report IHMT/5/97 is a report on the environmental assessment of the crash site.

Since responding to your initial FOIA request, reference FOI2018/06031 responded to on 29th May 2018, a further file of information relating to the loss of the Royal Danish Air Force (RDAF) F16 over Necton, Norfolk on 11th December 1996 has been located. It is with apologies that this material was not made available to you at the time of your earlier request; this was due to cataloguing errors at the Ministry of Defence storage facility.

As these documents have been considered for release under a subsequent FOIA request, they are attached for your information. The full list of attachments are as follows:

- Attachment A: Factual Information Regarding the Crash of a Danish F-16
- Attachment B: Enclosure 2- Danish Air Force F16 Accident on Departure from RAF Marham
- Attachment C: Enclosure 5- Update on Danish Air Force F16 Accident
- Attachment D: Enclosure 12- Report on the Recovery of an RDAF F-16 Trainer
- Attachment E: RAF Institute of Health and Medical Training Report IHMT/5/97

Section 40(2) has been applied across the attachments in order to protect personal information as governed by the General Data Protection Regulation 2018. As *Section 40 (2)*

is an absolute exemption, there is therefore no requirement to consider the public interest in making a decision to withhold the information. The names and contact details of officials in the Senior Civil Service (SCS) and their military equivalents (Commodore, Brigadier, Air Commodore and above) are considered to be available in the public domain and have not been redacted.

Section 44 (1) a, applied in Attachment B, relates to the release of information by the public authority holding the information if disclosure is prohibited by or under any enactment. Once more, *Section 44 (1) a* is an absolute exemption, in this instance the exemption is applied to personal medical information.

Attachment A is a synopsis of information provided by the RDAF in September 2018. The exemption accounted for at *Section 27 (3) (International Relations- information obtained from a state where the circumstances in which it was obtained make it reasonable to expect that it will be held in confidence).* of the FOIA was upheld. *Section 27 (3)* is a qualified exemption and therefore subject to a Public Interest Test (PIT). The PIT found that the public interest in maintaining the confidence of the Royal Danish Air Force (RDAF) outweighed the interest in releasing documentation, held by the Ministry of Defence, which originated with the RDAF.

Under *Section 16* of the Act (Advice and Assistance) you may find it helpful to note that the contact details for the Royal Danish Air Force are below:

Website:

<https://www2.forsvaret.dk/eng/Organisation/AirForce/Pages/RoyalDanishAirForce.aspx>

E-mail: vfk@mil.dk

Address:

Defence Command Denmark,
Air Staff
Herningvej 30
DK-7470 Karup J.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <http://www.ico.org.uk>.

Yours sincerely,

Air Historical Branch (RAF)

11 Dec AIR TRAFFIC CONTROL

Danish F-16 A Danish F-16 fighter aircraft crashed shortly after take-off from RAF Marham. The 2 man crew ejected shortly after take-off and the aircraft eventually crashed near the village of Necton, some 15km after the crew ejected. The aircraft fortunately came down in a field and there was no loss of life or damage to civil property apart from a large hole approximately 30 feet deep.

Under Section 16 of the Act (Advice and Assistance) you may find it helpful to note that the contact details for the Royal Danish Air Force are below:

Website:

<https://www2.forsvaret.dk/eng/Organisation/AirForce/Pages/RoyalDanishAirForce.aspx>

E-mail:

vfk@mil.dk

Address:

Defence Command Denmark,
Air Staff
Herningvej 30
DK-7470 Karup J.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <http://www.ico.org.uk>.

Yours sincerely,

Air Historical Branch (RAF)

RESTRICTED

LOOSE MINUTE

D/Sec(AS)/58/1/36

11 December 1996

PS/USofs*

* by CHOTS

copy to:

APS/Secretary of State*

APS/Minister(AF)*

APS/Minister(DP)*

PS/CAS*

PSO/ACAS

AUS(H&O)

Redacted - Sect. 40

Press Secretary*

Sec(AS)2*

HCDC Liaison Officer*

STC - CS(P&P)1

Chief Claims Officer*

Air Attache, Copenhagen

ROYAL DANISH AIR FORCE F-16 ACCIDENT - 11 DEC 96

1. I am writing to confirm the details of this morning's accident involving a two-seat F-16B aircraft of the Royal Danish Air Force (RDAF).
2. The aircraft arrived at RAF Marham on 5 December on a routine liaison visit but bad weather delayed the originally planned departure until this morning. Shortly after becoming airborne and with the aircraft in a steep climb, the crew encountered difficulties and ejected. The trajectory of the aircraft was such that it crashed in open farmland some seven miles away, just outside the village of Necton. The crew was picked up by a SAR helicopter and taken to King's Lynn Hospital having sustained only minor injuries. Early suggestions are that the accident may have been caused an engine failure.
3. Post-crash management personnel at the site are alert to the presence of a highly toxic, flammable chemical compound known as Hydrazine (H_4N_2) which the F-16 uses during the engine start-up sequence. Although only a small amount of the substance is carried, it can cause systemic poisoning and permanent kidney damage if improperly handled. RAF firecrews and personnel at the Aircraft Recovery & Transportation Flight are trained accordingly. In addition, RAF personnel detached to the scene immediately after the accident occurred took additional advice from United States Air Force personnel at RAF Lakenheath, who are more familiar with F-16 post crash management procedures.
4. NATO arrangements for investigating military aircraft accidents permit the authority owning the aircraft to investigate the crash if no other aircraft is involved. Accordingly, the RDAF will be investigating this accident and is setting up its own Board of Inquiry; a RAF observer will be in attendance.

RESTRICTED

RESTRICTED

5. I attach a draft letter for USofS to send to Gillian Shepherd, the MP in whose constituency the accident occurred. I do not believe that there is a requirement for the Department to advise the HCDC of this accident as although accidents to foreign aircraft were not specifically excluded from the reporting arrangements agreed earlier this year, the Committee's interest was focused on UK military aircraft losses and our inquiry procedures neither of which are, of course, relevant here. I also attach some defensive press lines.

Redacted - Sect. 40

RESTRICTED

DRAFT LETTER TO GILLIAN SHEPHERD MP

I am writing to confirm the details of the aircraft accident which occurred in your constituency this morning.

A two-seat F-16B aircraft of the Royal Danish Air Force had just taken off from RAF Marham, bound for Denmark, when the crew encountered difficulties and ejected. The aircraft crashed some four miles east of Swaffham. The crew were subsequently picked up by a RAF helicopter having sustained only minor injuries.

The investigation into this accident is being carried out by the Royal Danish Air Force under the terms of a NATO Standardization Agreement.

THE EARL HOWE

Rt Hon Gillian P Shepherd MP

PRESS LINES ON AIRCRAFT ACCIDENT INVOLVING A RDAF F-16B - SWAFFHAM
- 11 DEC 96

- Confirm that a two-seat F-16B of the Royal Danish Air Force has crashed seven miles east of RAF Marham.
- The aircraft had just departed Marham and was intending to return to Denmark when the crew encountered difficulties and ejected. They were subsequently picked up by SAR helicopter having sustained only minor injuries.
- The Royal Danish Air Force has convened a Board of Inquiry at which the RAF will have an observer.


If pressed:

- The aircraft was in a steep climb when the crew ejected and the trajectory of the aircraft was such that it continued to travel some distance before crashing into open farmland. It is entirely normal practice for F-16s to enter into a steep climb upon departure.

- It will be a matter for the Danish authorities whether they wish to make the findings of their Inquiry public.

- Confirm that F-16 aircraft carry a small amount of Hydrazine, which is used during the aircraft's start-up sequence. As with any chemical compound, Hydrazine is entirely safe provided it is handled only by trained and properly equipped professionals.

- We are not aware of any claims arising from this accident but any that we receive will be considered fairly and objectively.



Aircraft
Crash Site

Necton
Wood

Lodge Farm

SANDS

24/2 Norfolk County Council sent us information regarding new contact personnel due a change in the structure of their Planning and Transportation Department.

28/2 We received a letter from Gillian White of the Ministry of Defence, regarding the aircraft crash in Necton parish. The investigation into the crash was being dealt with by the Danish authorities and therefore our M.O.D. were unable to comment, but to say that they were sorry that our parish council felt that communication had been poor. They did not agree but thanked us for our comments.

4/3 The clerk telephoned Steve O'Brien, Breckland Council's Dog Warden, and asked about dog waste bins. These, he was told, would be bought by the parish council, put in by Breckland in a position which we would decide, and Breckland would also empty the bins fortnightly. But, sadly, a councillor would have to fit the bin with a bag each time it had been emptied.

4/3 The clerk had telephoned Mike Norton Breckland Council's Grounds Maintenance Officer regarding a hedge at the bottom of Chantry Lane which needed cutting back.

4/3 A sarcastic letter had been sent to P.E.Ryder in reply to their letter asking for information regarding the wattages of the lights in the village. "We thought you were supposed to know that!"

4/3 A donation of £25 had been sent Dereham and District Citizens Advice Bureau.

4/3 A copy of the letter which we had received from A.E.Timol of the Home Office, Juvenile Offenders Unit, which conveyed their policies in the area of juvenile crime, was sent to the Inspector at Swaffham Police Station, so that we could keep him informed of the situation. We also added words of praise for P.C.Yeouens work in the village.

4/3 Chris Warren of Breckland Council Land Drainage Department was written to, to ask that a ditch in Chantry Court be cleared out.

4/3 Mr Townly at Norfolk County Council was written to, to ask that something be done about the footpath outside 8, Burnside which had sunk. Also our thanks were offered for all of his hard work, we offered him all the best in his new placement.

5/3 Altered timetables for the Watton-Swaffham Norfolk Green Bus Service had been sent to us from Norfolk County Council.

The cheques were approved by the councillors.

A list of the chairman's expenses were also approved by the councillors.

Any Other Business: Councillor Cox told the clerk about a street light outside the Middle School gate which was out, and then councillor Jenkins told him about street light No.120 in Elizabeth Drive which was on all day. The clerk promised to report these to the Electricity Board.

The vice-chairman then spoke to the meeting about his concerns regarding the fighter aircraft crash in the parish on 11th December last year and the activities which have taken place, apparently as part of the investigation into the crash. Councillor Bartholomew said that he was greatly troubled by the large amount of soil which has been cleared from the crash site in lorry load after lorry load. The farmer whose field the aircraft landed in has been told that he cannot grow any crops in that field for a minimum of one year. This, the vice-chairman said, was due to a hydrazine chemical which had been carried on board the aircraft. The general consensus of opinion amongst the council was that we should keep probing to see if we can find out any more information about the reasons for the crash and what the results of the crash could be and indeed could have been, had the aircraft have landed in a built up area.

The clerk was asked to contact Mr Ryder at Breckland Council so that an April date when he, councillors or the clerk and Mr Peter Tattersall of Necton Parochial Church Council can meet to discuss the illumination of the church, its cost and the chances of a grant being raised to help with the outlay. Griston church has recently been illuminated and this has put an instant stop to vandalism. Councillor Bass commented that a shrub is hitting cars as they pass opposite the butchers. Councillor Woodward asked if the Electricity Board had replied regarding the blue flashes outside 57, Jubilee Way. We had not.

The chairman then told the council that pallets are still being sold at the Hungry Horse, despite Dereham planning office's efforts to stop it. She has telephoned planning and complained, and asked any councillors whenever in Dereham to go into the planning office to have a moan about it. the chairman is to see the Breckland representative about the matter.

Next Meeting: is on Thursday 24th April at 7:30 p.m. at Necton Village Hall.

Meeting Ended: at 8:43 p.m.

From: Mrs S Gardiner



Ministry of Defence
Main Building (Ground Floor, Zone D)
Whitehall
London SW1A 2HB
United Kingdom
Telephone [MOD] +44 (0)20 721 89000
E-mail: CIO-FOI-IR@mod.uk

Head - Information Rights Team

FOI2018/06031 & 11881

Ms J Smedley
Via e-mail: [REDACTED]

th
10 January 2019

Dear Ms Smedley

ENVIRONMENTAL INFORMATION REGULATIONS (EIR) 2004 – INTERNAL REVIEW

1. I am writing in response to your email of 9 October 2018 in which you requested an internal review of the processing of an information request initially handled by the Air Historical Branch (AHB) of the Royal Air Force, under the Freedom of Information (FOI) Act. The purpose of this review is to consider whether the requirements of the relevant Information Rights legislation have been fulfilled. The scope of internal reviews are defined by Part VI of the Code of Practice under section 45 of the Act, at: https://www.gov.uk/government/uploads/system/uploads/attachment_data/file/235286/003_3.pdf, or for the Environmental Information Regulations at https://ico.org.uk/media/for-organisations/documents/1613/internal_reviews_under_the_eir.pdf. This is my formal response following the review. I am sorry for the delay in responding.

Review Considerations

2. I note that request FOI2018/11881, relates to information provided under a previous request (FOI2018/06031, which you submitted on 2 May 2018). As the two requests are clearly linked, I have extended the scope of my review to cover the handling of both cases.

3. Although previously handled under the FOI Act ('the Act'), I have determined that that your requests should have been processed under the Environmental Information Regulations (EIR) because the information in scope of your request falls under the definition of environmental information. Regulation 2(1) of EIR defines environmental information as "any information in written, visual, aural, electronic or any other material form on –

(a) the state of the elements of the environment, such as air and atmosphere, water, soil, land, landscape and natural sites including wetlands, coastal and marine areas, biological diversity and its components, including genetically modified organisms, and the interaction among those elements;

Plane Crash Report – Additional

During the process of answering questions regarding the withholding of the Royal Danish Air Force crash report, the MOD has confirmed that several organisations ('a competent person', the Defence Land Agency, the DCRO and the PHMDiv – Public Health Monitoring) were selected to organise and carry out continued monitoring of the crash site for an indeterminate length of time. However, the MOD were unable to provide any evidence, documents or records to show that such monitoring was ever carried out, or that the area was ever signed off as contamination free.

c. A monitoring strategy should be set up by a competent person, in consultation with the Defence Land Agency, to continue to assess the whole area for further environmental impact, including the possibility of carbon fibres (if any) entering the food chain and the biodegradation of the aviation fuel on agricultural land."

5

Para 20 also states:

"Following the meeting between the DCRO, the Defence Land Agent, the farmer and the farmer's agent during the handover of the field, the pollution monitoring team from PHMDiv have been tasked to carry out further monitoring of the site of the F16 aircraft crash in the arable field for any adverse environmental effects and the reemergence, if any, of carbon composite fibres"." Document - Q - 20180110-Rev-Smedley-Contamination left behind from Danish F-16 crash-Rev response – 22

The MOD representative goes on to say: "I can confirm that no other information has been found relating to any follow-up environmental assessments after January 1997. In addition, no information is held on the advice (if any) to the farmer or landowner about the future use of the land."

In the absence of any evidence to the contrary, the only safe option for residents of Necton and Ivy Todd is to assume that the monitoring was never completed. The whole area should now be re-tested by the relevant official body that holds ultimate responsibility for the monitoring, which appears to be PHMDiv before any 'for profit' developers are allowed to start disturbing the land any deeper than plough depth.

(b) factors, such as substances, energy, noise, radiation or waste, including radioactive waste, emissions, discharges and other releases into the environment, affecting or likely to affect the elements of the environment referred to in (a)”

There are further categories in the EIR but I consider Regulation 2(1)(b) to be the relevant one in this case, as your request seeks information about land contamination and its long-term management following the crash of a Royal Danish Air Force (RDAF) F16B on private land belonging to Mona Farm, Necton, Norfolk, on 11 December 1996.

4. The Regulations promote the release of as much environmental information as possible to enable increased public participation in environmental decision-making. I apologise that your information request was processed using the wrong information access regime. However, I am satisfied that the processing of your request under the Act has not materially affected the response provided, and has not placed you at any disadvantage.

5. In conducting my review, I have focussed on the following requirements of the EIR:

a. Para 5(1) which provides that a public authority holding environmental information shall make it available on request;

b. Para 5(2) which states that the information shall be made available no later than 20 working days after the date of receipt of the request;

c. Para 7(1) which provides that where a request is made under Regulation 5, the public authority may extend the period of 20 working days to 40 working days if it reasonably believes that the complexity and volume of the information requested means that it is impracticable either to comply with the request within in the earlier period or to make a decision to refuse to do so;

d. Para 7(3) which states that where para 7(1) applies, the public authority shall notify the applicant accordingly as soon as possible and no later than 20 working days after the date of receipt of the request;

e. Para 9(1) which states that a public authority shall provide advice and assistance, so far as it would be reasonable to expect the authority to do so, to applicants and prospective applicants.

Handling of FOI2018/06031

6. Your first request for information, received by the Department on 2 May 2018, was worded as follows:

'I am trying to find out some information about contamination that was left behind after a Danish RAF jet crashed in a field close to my house in Necton, Norfolk PE37 8HY on 11th December 1996. Can you help me with this please or point me in the right direction?

Local knowledge says that this is carbon fibre and/or depleted uranium from armaments.”

7. In accordance with Regulation 7(1), a substantive response was due no later than 1 June 2018. The response you received, dated 29 May 2018, met that statutory deadline and contained details of your right to appeal in the first instance to MOD and then, if still not content following internal review, to the Information Commissioner.

8. The response stated that a search for the information had been completed within Ministry of Defence (MOD) and it was confirmed that 'some' information in scope of your request was held. This took the form of a Loose Minute reference D/Sec(AS)/58/1/36, dated 11 December 1996, which was a written brief to the then Under-Secretary of State for Defence on the day of the crash, confirming details of the incident and the actions taken in follow-up, together with a draft letter for the Minister to send to the MP in whose constituency the crash had occurred, together with the press lines. You were also provided with the Air Traffic Control entry from the RAF Marham Operation Records Book (RAF Form 540) for the same day and given the contact details for the RDAF under section 16 of the Act (advice and assistance). The first document had three small redactions under section 40 of the Act to protect personal information.

9. This response met the timeliness requirements of the Act and EIR. As explained above, your request should have been processed under the EIR rather than the FOI Act. As such, I find that the information withheld under section 40 of the Act should have been withheld under Regulation 13 in the EIRs, which protects the release of personal information.

Handling of FOI2018/11881

10. Your second request for information, received by the Department on 19 September 2018, was worded as follows:

"Does the MOD have any information as to how long the farmer was advised to keep off the land, and the item recalled by our Parish Council, which stated that a major development on the land needed special permission."

11. In accordance with Regulation 7(1), a substantive response was due no later than 17 October 2018. The response you received, dated 21 September 2018, met that statutory deadline and contained details of your right to appeal in the first instance to MOD and then, if still not content following internal review, to the Information Commissioner.

12. Again, this response met the timeliness requirements of both the Act and EIR.

Substance of FOI2018/11881

13. This request specifically sought "*any information as to how long the farmer was advised to keep off the land*" and you were advised that relevant information was contained in the *RAF Institute of Health and Medical Training Report IHMT/5/97*, dated February 1997. The response explained that due to cataloguing errors at the MOD file storage facility, a file¹ had come to light that contained information which, had it been found at the time of the first request, would have been considered for release. The AHB apologised for this oversight and included the following information in their reply:

- Attachment A: Information Regarding the Crash of a Danish F-16;
- Attachment B: *Enclosure 2 – Danish Air Force F-16*;
- Attachment C: *Enclosure 5 – Update on Danish Air Force F-16 Accident*;

¹ STC/4599/2028/FS raised by Flight Safety, HQ Strike Command, RAF High Wycombe on 12 Dec 1996.

- Attachment D: *Enclosure 12 – Report on the Recovery of an RDAF F-16 Trainer*,
- Attachment E: *RAF Institute of Health and Medical Training Report IHMT/5/97*.

However, I note that these documents are a mixture of originals from the period of the crash and one that was created by the RDAF in response to UK MOD's contact with them about releasing the original Danish documents. As this document was not held by the Department at the time of your request, it should not have been considered for release:

- Attachment A, comprised the releasable extracts from two Danish documents otherwise redacted under section 27 (International Relations) attached to a final RAF report - see Annex D.
- Attachment B was a two-page loose minute addressed to Director Operations Strike Command from RAF Marham, dated 12 December 1996, and we released with some redactions under section 40 (personal information) and 44 (prohibition on disclosure). Attached to this was a third page that appears not to belong to the same document (although it was included in the release because shares the same enclosure number).
- Attachment C, was a one-page loose minute from RAF Marham, dated 20 December 1996, addressed to the Personal Staff Officer to the Air Officer Commander-in-Chief Strike Command (and other senior RAF officers); we released the content in full, apart from a small redaction under section 40 for the signature block.
- Attachment D was a final report following the recovery of the aircraft, dated 24 January 1997. It contains 22 pages in total. You were provided with the two-page cover note and the four pages of the report produced by the RAF with small redactions to protect personal data, under section 40. However, as mentioned above, you were not given access to two Danish reports, one of 10 pages from the Commission on Accidents in Flight, dated 6 January 201997 and another of 6 pages which covers the conclusions and recommendations of the RDAF into the causes of the accident. The Danish documents were partially disclosed in the form of releasable extracts (Attachment A) and the remainder of the information withheld under section 27 (International Relations).
- Attachment E was a report produced by the RAF Institute of Health and Medical Training Report IHMT/5/97 (13 pages), dated February 1997 and this was provided with small redactions for personal data under section 40.

Use of Section 27 (international relations)

14. I have carefully read through the two Danish documents to which this exemption was applied, and can confirm that the only environmental information they contain has already been provided to you as Attachment A to your second request.

15. As the remainder of the reports contain detail of the sequence of events during flight, the personal injuries sustained by the crew, information about the aircraft, the weather conditions, and conclusions and recommendations about future flying arising from the accident the information that was withheld under section 27 is not in scope of your request. The withheld material does not contain any information about the environmental impact of the crash, any long-term monitoring of the site or instructions to the land-owner.

16. I find that the Department has applied the exemption to information that is not in scope of your request. I apologise for this error and any inconvenience that may have been caused by the Department giving you the impression that the withheld material could have informed a public debate about any potential safety concerns relating to the proposed development of the crash site.

Relevant Environmental Information

17. Para 5(1) of the EIRs places a duty upon a public authority to search and retrieve *relevant information* that meets the description of the request. My understanding of FOI2018/06031 and FOI2018/11881, and the context for your requests provided in your correspondence with my team, is that you are seeking information about any contamination in the crash site, and any information about the long-term environmental management of the site. You are not seeking information about the causes of the crash, injuries sustained by the crew, details of the flight up to the point the crew ejected or recommendations that may have been made to improve flight safety for military pilots.

18. I have concluded that the Department chose to interpret your initial request as one for all information held in relation to the aircraft crash and the subsequent investigation into its cause. Having looked at the released documents and the two Danish documents which were withheld, I have concluded that most of the information held about the crash is not relevant to your specific enquiries.

19. I am sure all the documents provided to you, were intended to be helpful and they certainly provide useful background and context to the crash. However, the only relevant information in response to your original requests would be environmental. Under the EIRs, as with the Act, requesters are entitled to receive recorded information that meets the description of their request. I believe that a series of relevant extracts from the relevant documents might have been more helpful to your enquiries.

20. With these principles in mind, I have looked through the information (both withheld and held) and have extracted the information that meets the description of your request. This is attached to this review at Annex A.

21. With regard to 'Attachment E', I have concluded that the entire report is in scope of your request because it is an environmental assessment of the crash site produced by the RAF Institute of Health and Medical Training (IHMT). It records the visits to the site by the Public Health Medicine Division (PHMDiv) of the RAF IHMT, in association with the civil Environmental Health Department and the Duty Crash Response Officer (DCRO) on three occasions, during the period December 1996 to January 1997.

22. Of all the information held by MOD on the crash, I consider this the most relevant to your enquiries, as it contains a description of the assessed extent of the fuel contamination at the site and references to the need for future monitoring, I draw your attention to paragraph 17 in which it is stated that, amongst other recommendations:

"b. Arrangements should be made for the DCRO to return [to] the crash site to take part in the handover of the field to the farmer and his agent once it has been cleared of all contamination.

c. A monitoring strategy should be set up by a competent person, in consultation with the Defence Land Agency, to continue to assess the whole area for further environmental impact, including the possibility of carbon fibres (if any) entering the food chain and the biodegradation of the aviation fuel on agricultural land."

Para 20 also states:

“Following the meeting between the DCRO, the Defence Land Agent, the farmer and the farmer’s agent during the handover of the field, the pollution monitoring team from PHMDiv have been tasked to carry out further monitoring of the site of the F16 aircraft crash in the arable field for any adverse environmental effects and the re-emergence, if any, of carbon composite fibres”.

In order to meet the obligation to provide environmental information relating to the monitoring of the crash site, a more comprehensive search has been carried out of the department involving AHB(RAF), the MOD file store and the Defence Infrastructure Organisation (DIO – formerly the Defence Lands Agency). I can confirm that no other information has been found relating to any follow-up environmental assessments after January 1997. In addition, no information is held on the advice (if any) to the farmer or landowner about the future use of the land. However, the DIO can confirm that the site is not on any continuing monitor programme run by them and they are not aware of any restrictions on the future use of the site.

Use of exemptions

23. For the material released in response to your second request, I find that the only exemption necessary is Regulation 13 in the EIRs, to withhold personal information, principally the identities of the writers of the report and those mentioned by name in the text who were involved in the assessment visits.

Advice and assistance

24. The Contaminated Land Officer at the local authority, may hold information about known contaminated sites in their area and, if you have not already done so, it may be advisable to contact them with your request. Indeed, both Norfolk local councils maintain databases of such sites on their websites for public consultation. It is also possible that the Land Registry and the Environment Agency will hold relevant information.


Conclusion

25. In summary, I find that:

- The processing of this request did not focus on providing environmental information under the EIRs consequently, much of the information provided was not relevant to your enquiry;
- The initial processing under FOI Act rather than EIR has not materially affected the outcome of your information request;
- The responses met the timeliness requirements of both FOI and EIR;
- The information that was withheld under section 27 is not in scope of your request; all environmental information contained in the Danish reports has already been provided to you at Attachment A;
- A more comprehensive search of the department has been undertaken for relevant information as part of this review;
- Appropriate help and assistance has been provided.

If any aspect of this review is unclear, I would be happy to explain it. If you are dissatisfied with the review, you may wish to make a complaint to the Information Commissioner under the provisions of section 50 of the Act. Further details of the role and powers of the Commissioner can be found on the website at: <https://ico.org.uk> . The address is: Information Commissioner's Office, Wycliffe house, Water Lane, WILMSLOW, Cheshire, SK9 5AF.

Yours sincerely,



Mrs S Gardiner

Environmental Information in scope of FOI018/06031

Loose Minute Reference D/Sec(AS)/58/1/36, dated 11 December 1996

Paragraph 3, the first two sentences:

“Post-crash management personnel at the site are alert to the presence of a highly toxic, flammable chemical compound known as Hydrazine (H₄N₂) which the F-16 uses during the engine start-up sequence. Although only a small amount of the substance is carried, it can cause systemic poisoning and permanent kidney damage if improperly handled.”

Press Lines – If pressed, bullet three:

“Confirm that F-16 aircraft carry a small amount of Hydrazine, which is used during the aircraft’s start-up sequence. As with any chemical compound, Hydrazine is entirely safe provided it is handled only by trained and properly equipped professionals”

Attachment A

Paragraph 4:

“The accident spread carbon fiber [sic], hydrazine, oil products and some 6,000 lbs of fuel. The concentration of hydrazine was neutralized using chlorine products.”

Attachment B

Paragraph 4, final sentence:

“Crash site hazards are hydrazine, MMMF¹ and 200 rounds of 20mm ball ammunition.”

‘Para 7, final sentence:

“Testing for hydrazine has been completed and carbon fibre contamination has been found to be present on the site”.

Attachment C

While paragraph 2 of this document does refer to wreckage recovery teams ‘working to clear the site’, this relates to the removal of aircraft wreckage only. The document does not contain any information about possible environmental contamination or longer term environmental management of the site, and I do not consider it to be in scope of your request.

¹ MMMF = Man-Made Mineral Fibre (in this instance, carbon fibre)

Attachment D

Paragraph 2, fourth sentence:

"...it was quickly established that apart from the health and safety implications of hydrazine, aviation fuel and carbon composite fibres deposits, it should be a relatively straight forward recovery operation."

Paragraph 3, second and third sentence:

"On impact, it produced a 3m deep crater and spread aircraft wreckage and aviation fuel over a wide area of...sugar beet field. The crash site was also contaminated with hydrazine from the Emergency Power Unit (EPU) and burnt carbon composite fibres"

Paragraph 9, second, third and fourth sentence:

"They quickly located the aircraft's hydrazine tank, which had split open leaving several deposits within a 60 metre area down-slope from the crater. This area was deemed the inner cordon and only RDAF personnel were permitted to enter whilst the hydrazine threat was being alleviated by their specialist team. This lasted 3 days."

Para 11, first sentence:

"The site was declared safe from the hydrazine on 15 Dec 96."

Para 12, line 17:

"...in association with the DLA and IHMT, the ARO had all the contaminated soil removed to licenced tips."

Para 13 sub-titled "Environmental Health/Health and Safety at Work Aspects" beginning *"The Hydrazine hazard gave concern throughout the recovery"* and the whole of the rest of that paragraph ending: *"Protective equipment was used, as directed by the ARO, by the AR&TF team and the support personnel of RAF Marham and Coltishall."*

Attachment E

The entire report.

Environmental Information in scope of FOI018/11881

None

From: [Area Manager Correspondence, East Anglia](#)
To: [REDACTED]
Subject: RE: AMC/2018/1106 FW: 180606/BA10 FW: Radioactive matter
Date: 02 July 2018 09:47:00
Attachments: [image001.jpg](#)
[image002.jpg](#)
[image003.jpg](#)
[image004.jpg](#)
[image005.jpg](#)
[image006.jpg](#)
[image007.jpg](#)

Dear Ms Smedley,

Thank you for your email of 28 June 2018.

IPC (or ISC, (the copy is unclear)), appears to be an acronym used by the Ministry of Defence to denote a department or section within the command structure of the RAF. We have not seen it in any recent communications so unable to confirm what it meant then or now.

Kind regards

Stephanie

Stephanie Fullwood
Customers & Engagement Officer
Customers & Engagement Team
East Anglia Area
Environment Agency, Bromholme Lane, Brampton, Huntingdon, Cambs. PE28 4NE
☎ External Tel: 02030 251938
areamanagercorrespondence.eastanglia@environment-agency.gov.uk



[cid:image008.jpg@01D2E50F.9815A070](#)



CSE



From: [REDACTED]
Sent: 28 June 2018 11:26
To: Area Manager Correspondence, East Anglia
<AreaManagerCorrespondence.EastAnglia@environment-agency.gov.uk>
Subject: Re: AMC/2018/1106 FW: 180606/BA10 FW: Radioactive matter

Sorry Stephanie, the fax mentions IPC (that's what it looks like) could you tell me who they are please?

From: [Area Manager Correspondence, East Anglia](#)

Sent: Thursday, June 28, 2018 11:12 AM

To: [REDACTED]

FW: 180606/BA10 FW: Radioactive matter

Dear Ms Smedley,

Thank you for your email of 6 June 2018 to DEFRA. They have passed your enquiry to us for reply and will receive a copy of our response.

I have checked our records and it appears that we have already provided a response to you on this matter on 31 May 2018 under reference number EAn/2018/85361 and 5 June 2018 under reference number EAn/85361-1. Please find attached our final replies for your information.

Kind regards

Stephanie

Stephanie Fullwood

Customers & Engagement Officer

Customers & Engagement Team

East Anglia Area

Environment Agency, Bromholme Lane, Brampton, Huntingdon, Cambs. PE28 4NE

☎ External Tel: 02030 251938

areamanagercorrespondence.eastanglia@environment-agency.gov.uk



cid:image008.jpg@01D2E50F.9815A070



CSE



From: Jenny Smedley [REDACTED]

Sent: 06 June 2018 07:54

To: Helpline, Defra (MCU) <defra.helpline@defra.gsi.gov.uk>

Subject: Radioactive matter

Dear Sir

On 11th December 1996 a Danish Air Force F16 military jet crashed in Necton, Norfolk. (Ivy Todd) TF 894100 It was said on a fax (attached) that MAFF (yourselves at the time) was

notified of a radioactive material risk (assumed to mean uranium from the armaments) existed.

Now a developer is planning to build two massive substations and a cable corridor very close to the site. Can you tell us anything about the contamination risk to this area and whether it would be considered wise to build over or close to this area?

Thank you
Jenny Smedley

This message has been scanned and no issues were discovered.
Click [here](#) to report this email as spam

Information in this message may be confidential and may be legally privileged. If you have received this message by mistake, please notify the sender immediately, delete it and do not copy it to anyone else.

We have checked this email and its attachments for viruses. But you should still check any attachment before opening it.
We may have to make this message and any reply to it public if asked to under the Freedom of Information Act, Data Protection Act or for litigation. Email messages and attachments sent to or from any Environment Agency address may also be accessed by someone other than the sender or recipient, for business purposes.
Click [here](#) to report this email as spam

This message has been scanned and no issues were discovered.
Click [here](#) to report this email as spam

Information in this message may be confidential and may be legally privileged. If you have received this message by mistake, please notify the sender immediately, delete it and do not copy it to anyone else.

We have checked this email and its attachments for viruses. But you should still check any attachment before opening it.
We may have to make this message and any reply to it public if asked to under the Freedom of Information Act, Data Protection Act or for litigation. Email messages and attachments sent to or from any Environment Agency address may also be accessed by someone other than the sender or recipient, for business purposes.
Click [here](#) to report this email as spam

From: [REDACTED]
To: [Norfolk Boreas](#)
Subject: Re: Norfolk Boreas Project – EN010087
Date: 21 November 2019 11:07:09

Dear Examining Authority

In answer to this response from the developer:

<https://infrastructure.planninginspectorate.gov.uk/wp-content/ipc/uploads/projects/EN010087/EN010087-001224-Comments%20on%20Relevant%20Representations.pdf> Table 24

“Onshore project substation visual impact mitigation

Rep-109, AS-014 The Applicant will work to ensure that mitigation proposed is proportional to the scale of the substation infrastructure, and that it mitigates the overall impact on the local area. The final design of the onshore project substation and National Grid substation extension are subject to detailed design post-consent. In order to minimise visual impacts as far as possible, the appropriate building design and materials will be considered, to ensure blending with the local environment and minimisation of impacts as far as possible.”

I have to return to the Vanguard PEIR – Chapter 29 - Table 29.18

Where it states categorically:

“The **local landscape character would be directly affected by the presence of the onshore project substation**, with its maximum footprint of 250m x 300m and its maximum height of 25m. This would form a large fenced site containing electrical infrastructure, the most notable component being the HVDC converter halls. Their **scale and mass would appear at variance** with the scale and character of the rural landscape. Despite the extent of mitigation planting around the onshore project substation, it would be **insufficient in scale to reduce the landscape effect within the operational period.**”

And yet we now have the developer promising that mitigation will be proportional to the scale of the substation, and that they will ensure that it blends in with the local environment. How? It's a simple question.

You will note that the PEIR also quotes the highest point of the structures as being 25m, not 19m. This is because it includes the lightning conductors which will be attached to each and every building of the project. The fact that the height is generally referred to now by almost everyone as being 19m, demonstrates the developers skill at misdirection.

These lightning conductors will have a great impact because of their height and because of the materials they will be composed of. They will no doubt sparkle in the sun. And yet there seems to be NO real design detail on them. No-one at any presentation (including the developer) could really understand if there is also a mesh connecting all conductors. If there is this mesh could create an even worse visual effect and also present a danger to wildlife.

There needs to be a better representative design done, with correct scale, including the 25m high conductors.

Without these details and answers being available at public presentations during the consultation, how can it be thought that the consultation was sufficient?

These kind of discrepancies populate this whole project, Vanguard and Boreas, and are then swept under the carpet later in proceedings. With respect to the EA, this money-making destruction of our county/country should be put on hold until other methods such as an ORM are online and the destruction can be avoided.

Time would appear to be against us, however, the developer has not even won an auction yet.

They will likely not be ready to start work (if approved) until 2022/2023.

Even then the development is expected to take 10 years.

With the onshore element largely removed, (as in with a set up ORM or interconnector system) the developer would save not only a vast sum of money, but would also save a great deal of time.

Jenny Smedley