

Figure 17.31: Proposed mitigation measures to provide the required standard of protection to the site from tidal overtopping.

