

From: [REDACTED]
To: [East Anglia ONE North](#); [East Anglia Two](#)
Subject: Friston House ASI1 Flooding report and photographs EAO 10077 ref: 20023661 EAO10078 ref: 20023663
Date: 03 February 2021 15:55:32
Attachments: [Friston House Grade 11 ASI1 EAO10077 +EAO10078.pdf](#)









ENO 10077 + ENO 10078

S Fulford



EA1 20023661



EA2 20023663

03/02/2021

Re Flooding and Infiltration estimates by the applicant.

I attach photographs taken the morning after one night of rain immediately after site inspection ASI1 when no surface water was present. The photographs are from site 6 (waterlogged field) and site 1 + 2 from the ASI1 on the 26/01/2021

This illustrates the lack of or low level of infiltration in contradiction of the applicants desk top models of infiltration with reference to the site of Friston.

I also attach photographs of the road B1121 outside  and the drive of  which again illustrate the flooding aspects of Friston after one night of rain during the winter months. This has become a frequent feature over the last few years.

S Fulford