

Image 13.1: View of Elmesthorpe Church, ruined nave and west tower scheduled monument (1005076), as experienced from the B584 Station Road to the south, at its junction with Bridle Path Road.



Image 13.2: View north from Burbage Common Road, within the northern edge of the DCO Main Site, illustrating the typical glimpsed experience of Elvesthorpe Church, ruined nave and west tower scheduled monument (1005076), as one moves along the road.



Elvesthorpe Church Scheduled Monument

Image 13.3: View north from Burbage Common Road, within the DCO Main Site close to Woodhouse Farm, looking over the field of ridge and furrow and illustrating the typical glimpsed experience of Elmesthorpe Church, ruined nave and west tower scheduled monument (1005076), as one moves along the road.



Elmesthorpe Church Scheduled Monument

Image 13.4: View north from Burbage Common Road, at the eastern end of the road within the DCO Main Site, illustrating the typical glimpsed experience of Elmesthorpe Church, ruined nave and west tower scheduled monument (1005076), as one moves along the road.



Elmesthorpe Church Scheduled Monument

Image 13.5: View north from PRoW V50/1 looking towards Elmesthorpe and illustrating the typical experience of Elmesthorpe Church from these PRoW south of the settlement, where the ruined nave and west tower scheduled monument (1005076) is nestled in to the hillside vegetation and screened by built form, such that there are no clear views, only occasional glimpses, of the monument as one moves through the lower-lying landscape.



Elmesthorpe Church Scheduled Monument

Image 13.6: The view west from the graveyard of the Elmesthorpe Church Scheduled Monument, illustrating how there is no visibility of the Church of St Mary, Barwell, to the east, with views in this direction curtailed by vegetation. This is not a view that looks towards the Main HNRFI Site.



Image 13.7: The view east from the churchyard of the Church of St Mary, Barwell, illustrating the enclosing nature of the vegetation within the curtilage of the church as well as the presence of residential properties beyond, which prohibit any visibility towards the Elmesthorpe Church Scheduled Monument to the east. This is not a view that looks towards the Main HNRFI Site.



Image 13.8: Typical outward view south-east in the direction of the DCO Main Site from the churchyard of the Church of St Mary, Barwell, illustrating the enclosing nature of the vegetation within the curtilage of the church, which prohibits clear views to the DCO Main Site. Photoviewpoint 19 (Document Reference 6.3.11.10) illustrates the clear views from the PRoW directly south of the churchyard towards the DCO Main Site.





Image 13.9: Typical outward view north-east in the direction of the DCO Main Site from the churchyard of the Church of St Catherine, Burbage, illustrating the enclosing nature of the vegetation within the curtilage of the church, and the built form of the surrounding settlement, which prohibits any views to the DCO Main Site. This image also illustrates how this enclosing built form and vegetation ensures there is no visibility from this church to any other churches in the landscape, including the Church of St Simon and St Jude, Earl Shilton to the north-east.



Image 13.10: Typical experience of the Church of St Catherine, Burbage from the DCO Main Site, which is limited to the distant glimpse of the spire in the view south-east from Burbage Common Road, close to the railway bridge.

Church of St Catherine, Burbage



Image 13.11: Typical outward view south-east in the direction of the DCO Main Site from the right of way U46/2 crossing the field immediately south the churchyard of the Church of St Mary, Barwell. This image illustrates how, from the low-lying land south of the church, there is no experience of the main HNRFI Site.



Image 13.12: The view north from the PRoW (U46/1) directly south of the Church of St Mary, Barwell, showing the church tower rising above enclosing vegetation. Further south, this vegetation and the boundaries of the lower-lying land ensure that the church is not a feature as one travels through these rights of way north of the main HNRFI Site.



Image 13.13: View from Burbage Common Road, within the DCO Main Site, looking north-west and illustrating the typical glimpsed experience of the Church of St Mary, Barwell on the horizon as one moves along the road.



Church of St Mary, Barwell

Image 13.14: Typical outward view south in the direction of the DCO Main Site from the churchyard of the Church of St Simon and St Jude, Earl Shilton, illustrating the enclosing nature of the church's immediate setting and how surrounding built form and vegetation prohibits any views to the DCO Main Site or to other churches in the landscape, including the Church of St Catherine, Burbage.



Image 13.15: View from Burbage Common Road, within the DCO Main Site, looking north and illustrating the typical glimpsed experience of the distant spire of the Church of St Simon and St Jude, Earl Shilton on the horizon as one moves along the road.



Church of St Simon and St Jude, Earl Shilton

Image 13.16: View from Burbage Common Road, within the DCO Main Site close to Woodhouse Farm, looking north over the field of ridge and furrow, and illustrating the typical glimpsed experience of the distant spire of the Church of St Simon and St Jude, Earl Shilton on the horizon as one moves along the road.



Church of St Simon and St Jude, Earl Shilton