

Submission ID: 32222

In regards with cable laying depth, I think its important to make sure all cables are at a depth no less than 1.2m deep. This is partly because when using heavy machinery, (sugar beet/potato harvesters) in wet conditions they can sink and cause deep ruts, which could cause damage to cables if too shallow.