

A19 Downhill Lane Junction Improvement Scheme Number: TR010024 7.6(1) Application Documents Errata

APFP Regulation 5(2)(q)

Planning Act 2008

Infrastructure Planning (Applications: Prescribed Forms and Procedure)

Regulations 2009



Infrastructure Planning

Planning Act 2008

The Infrastructure Planning (Applications: Prescribed Forms and Procedure) Regulations 2009

A19 DOWNHILL LANE JUNCTION IMPROVEMENT

The A19 Downhill Lane Junction Development Consent Order 202[]

APPLICATION DOCUMENTS ERRATA

Regulation Number:	Regulation 5(2)(q)
Planning Inspectorate Scheme	TR010024
Reference	
Application Document Reference	TR010024/APP/7.6(1)
Author:	A19 Project Team, Highways England &
	Jacobs

Version	Date	Status of Version
Rev 1	September 2019	Updated for Examination Deadline 2
Rev 0	July 2019	Post Application Issue



Page Left Intentionally Blank



CO	NT	ΕN	TS
----	----	----	----

1	INTRODUCTION1
2	SCHEDULE OF PLANS INCLUDED IN THIS APPLICATION DOCUMENT3

APPENDIX A – Figure 7.1 Rev 1



Page Left Intentionally Blank



1 INTRODUCTION

- 1.1 Following a check of the published DCO application documents on the Planning Inspectorate's website, errors have been found within some of said documents. Accordingly, the purpose of this document is to identify corrections needed to other DCO application documents.
- 1.2 The documents where errors were identified are as follows: -
 - TR010024_APP_6.3 Environmental Statement Appendices
 - TR010024_APP_7.4 Transport Assessment Report
 - TR010024_APP_6.2 Environmental Statement Figures Chapter 7



Page Left Intentionally Blank



2 SCHEDULE OF ERRORS & CORRECTIONS

DCO Document	Location of Error	Page		Corre	ection
TR010024_APP_6.3 - Environmental Statement – Appendices – Rev 0	Chapter 9 - Appendix D – Breeding Bird Report	22 (of Breeding Bird Report)	Missing reference in first line of Appendix D should refer to footnote 1 which is located on Page 1 of the Breeding Bird Report.		
TR010024_APP_6.3 - Environmental Statement – Appendices – Rev 0	Chapter 9 - Appendix D – Wintering Bird Report	22 (of Wintering Bird Report)	Missing reference in first line of Appendix D should refer to footnote 1 which is located on Page 2 of the Wintering Bird Report.		
TR010024_APP_7.4 - Transport Assessment Report – Rev 0	Paragraph 3.7.5	22	Paragraph should read as follows:- "For the reasons set out in 3.11.12 to 3.11.14,"		
TR010024_APP_7.4 - Transport Assessment Report – Rev 0	Paragraph 3.11.1	27	Paragraph should read as follows:- "For the reasons set out in 3.11.12 to 3.11.14,"		
	Figure 7.1	N/A	Old/Figure	New/Text	Asset Name
			83	28	Downhill Farmhouse
			84	30	Pair of Lodge Cottages at entrance to Downhill house
TR010024_APP_6.2 Environmental Statement Figures -			85	31	Barn and Gin Gang to South of Downhill Farmhouse
Chapter 7 – Rev 0			86	33	Limekiln Southeast of Downhill Farmhouse
			87	35	Downhill House
			The figure has been corrected to reflect Table 7-6 in Chapter 7 of the Environmental Statement		
			(TR010024/APP/6.1) [APP-020]. Accordingly, an		
					gure 7.1 (Rev 1) which
			includes the historic building references outlined		



A19 Downhill Lane Junction Improvement
Application Documents Errata

	above can be found in Appendix A.
	abovo dan bo round in Appondix 71.



APPENDIX A

Planning Inspectorate Scheme Ref: TR010024 Application Document Ref: TR010024/APP/7.6(1) (Volume 7)

