

The Inspectors appear not to have viewed or considered the affects of the application traffic on the Long Street New Road Coop roundabout. The applicant proposed no works to this junction because no works are possible. This junction is already at capacity at peak times and the Inspectors should ask for flow projections for it and should view it at peak times 0800-0900 and 1600-1800.