



Hornsea Project Three Offshore Wind Farm

Accompanied Site Inspection (ASI) Itinerary

Date: Monday 28 January 2019
Time: 9:00am – 3.40pm (approximate finish time)
Meet at: The car park at Lakenham Hewett RFC, Main Rd, Swardeston, Norwich NR14 8DU

Participants should meet at the above address between 9:00am and 9:30am. If you are arriving by car please park at the far south end of the car park. There will be a safety briefing at 9:30am before we proceed to the first location.

The ASI will involve the use of a vehicle and will include some walking. All attendees should wear sturdy footwear and appropriate clothing for the weather.

The ExA would like to remind all participants that the site inspection is not an opportunity to make any oral representations on the application. The purpose is to see physical features that are relevant to the examination.

The Applicant has provided a route for the ASI which the ExA has agreed with. Please note that the itinerary is indicative and therefore it is not possible to predict exactly how long each part of the visit will last or when particular sites will be visited. The itinerary can be found below.

Accompanied Site Inspection Itinerary

Stop	Time	Location
1	9.00am to 09.30am	Meet at Lakenham Hewett RFC. Safety briefing at 9.30am.
2	9.40am	Substation/Converter Option B
3	10.15am	House on the Hill
4	10.50am	Gowthorpe Manor
5	11.20am	Substation/Converter Option C
6	11.55am	Break at Tesco A140
7	12.35	Mangreen Hall
8	1.15pm	Substation/Converter Option A
9	1.45pm	Substation/Converter Option D
10	2.15pm	Keswick Hall
11	2.55	Intwood Hall
12	3.40	Finish at Lakenham Hewett RFC