

**AQUIND Interconnector**

**PINS Reference EN020022**

**Consultation Report Appendices: Errata sheet**

Appendix Reference	Amendment
5.1.1M	Addition of Cover Letters.
5.1.2A	Addition of DCO Press Release (July 2018), removal of Cover Letter (August 2018)
5.1.2B	Addition of Cover Letter (August 2018), removal of DCO Press Release (July 2018)
5.1.3G	Addition of Information Leaflet (October 2018)
5.1.4K	Section 42 Cover Letter removed, and Informal SoCC Reponses added.
5.1.4N	Addition of Formal SoCC Consultation Responses from PCC, WCC, HBC, EHBC responses.
5.1.4P	Updated Consultation Report paragraph references.
5.1.5G	Addition of Harbour Posters in situ
5.1.7I	Re-references as 5.1.7I (previously two 5.1.7H's)