

H2Teesside Project


Planning Inspectorate Reference: EN070009

Land within the boroughs of Redcar and Cleveland and Stockton-on-Tees, Teesside and within the borough of Hartlepool, County Durham

The H2 Teesside Order

Document Reference: 8.23 Draft Itinerary for ASI3

Planning Act 2008



Applicant: H2 Teesside Ltd

Date: November 2024

DOCUMENT HISTORY

DOCUMENT REF	8.23		
REVISION	0		
AUTHOR	BP		
SIGNED	EI	DATE	20.11.24
APPROVED BY	BP		
SIGNED	EI	DATE	20.11.24
DOCUMENT OWNER	BP		

CONTENTS

1.0	H2TEESSIDE ACCOMPANIED SITE INSPECTION 3 ITINERARY – 17TH DECEMBER 2024	2
1.1	ASI Itinerary.....	2
1.2	Notes on Itinerary	3

TABLES

Table 1.1: Suggested ASI locations and timings	2
--	---

FIGURES

Figure 1.1: Map showing suggested ASI3 Locations	4
--	---

1.0 H2TESSIDE ACCOMPANIED SITE INSPECTION 3 ITINERARY – 17TH DECEMBER 2024

1.1 ASI Itinerary

1.1.1 This Draft Accompanied Site Inspection 3 ('ASI3') Itinerary has been developed on the basis of the Applicant's experience of what is feasible to visit in a single day. This ASI Itinerary includes the outstanding locations which were suggested by Interested Parties (IPs) in their submissions at Deadline 1 and Deadline 2 but it was not logistically possible to include in the in the final itinerary for ASI1 [REP3-005] and it was also not logistically possible to visit during ASI 2 on 15 November 2024.

1.1.2 The timetable below is based on a start time of 08:00 in view of the more limited daylight hours in December (sunset will be around 15:39) with a meeting point at the Wilton Centre (TS10 4RF). The locations listed in **Table 1.1** below are shown indicatively on **Figure 1.1** at the end of this document.

Table 1.1: Suggested ASI locations and timings

NO.	LOCATION/ITINERARY ITEM	TIMING
1	Meeting point at Wilton Centre Car Park	08:00
2	Change into PPE	08:00 – 08:15
3	Safety briefing	08:15 – 08:30
4	Drive to Visitor Induction Centre and collection of passes	08:30 – 09:00
5	Drive to Wilton International Sembcorp Site	09:00 – 09:05
6	Walk around Wilton International Sembcorp Site to see how the Order Limits interact with Sembcorp activities	09:05 – 09:40
8	Comfort break at Sembcorp Wilton International Office	09:40 – 09:50
9	Drive to CF Fertilisers main site	09:50 – 10:20
10	Walk around CF Fertilisers main site to see how the Order Limits interact with their activities	10:20 – 10:50
11	Drive to Navigator Terminals link line corridor	10:50 – 11:00
12	Walk along Navigator Terminals link line corridor where it exits the Tunnels	11:00 – 11:30
13	Drive to RSPB Saltholme Café	11:30 – 11:45
14	Lunch at RSPB Saltholme Café	11:45 – 12:45
15	Drive to Cowpen Bewley AGI	12:45 – 13:00

NO.	LOCATION/ITINERARY ITEM	TIMING
16	Walk at to Cowpen Bewley AGI	13:00 – 13:30
17	Drive to Wilton Centre	13:30 – 14:00
18	Change out of PPE	14:00 – 14:15
19	Close	14:15

1.2 Notes on Itinerary

1.2.1 The following should be taken into account by those attending the ASI:

- Completion of online safety inductions (links will be emailed to attendees closer to the date via PINS).
- Attendees will need an ID (e.g. driving licence) on them to gain access to the Wilton International site.
- All electronic devices should be stored safely in vehicles or at lockers at the Wilton Centre.
- The following Minimum PPE will be required to attend the ASI:
 - Safety helmet
 - Safety glasses / over glasses / safety prescription spectacles
 - Anti-static safety boots
 - Anti-static flameproof overalls
 - Safety gloves.

Figure 1.1: Map showing suggested ASI3 Locations

