

Lower Thames Crossing

1.6 The Errata Report (Tracked changes version)

APFP Regulation 5(2)(q)

Infrastructure Planning (Applications: Prescribed Forms and Procedure) Regulations 2009

Volume 1

DATE: December 2023 DEADLINE: 9.

Deleted: 8

Planning Inspectorate Scheme Ref: TR010032 Application Document Ref: TR010032/APP/1.6

VERSION: 7.0

Revision History

Version	Date	Submitted at
1.0	20 December 2022	Response to advice provided under section 51 of the Planning Act 2008 by the Planning Inspectorate
2.0	18 July 2023	Deadline 1
3.0	24 August 2023	Deadline 3
4.0	19 September 2023	Deadline 4
5.0	31 October 2023	Deadline 6
6.0	5 December 2023	Deadline 8
7.0	11 December 2023	Deadline 9

Lower Thames Crossing

1.6 The Errata Report (Tracked changes version)

List of contents

_	_
Page	number

1_	Erra	ta	<u></u> 1
	<u>1.1</u>	Introduction	<u></u> 1
	1.2	Relationship to other documents	<u></u> 1
	1.3	Approach to Errata	2
App	endic	es	<u></u> 27
Δnr	andiv	A HRA Figure 24	28

Deleted: ¶
1 Errata 1¶
1.1 Introduction 1¶
1.2 Relationship to other documents 1¶
1.3 Approach to Errata 2¶
Appendices 27¶
Appendix A HRA Figure 24 28¶
¶

Lower Thames Crossing – 1.6 The Errat	a Report
(Tracked changes version)	

Volume 1

List of tables

Page number

Table 1.1 Errata identified within the submission documents

Deleted: Table 1.1 Errata identified within the submission documents 3¶

List of figures

HRA Figure 24

1 Errata

1.1 Introduction

- 1.1.1 This document is to present any errata that have been identified within the documents that were submitted as part of the DCO Application and through the Examination for the A122 Lower Thames Crossing (the Project).
- 1.1.2 The errors are minor in nature and do not change the meaning of documents, analysis or any assessment.
- 1.1.3 The Errata Report was first submitted with the S51 Submission in December 2022 [AS-004] in response to the S51 Advice issued by the Planning Inspectorate in November 2022 which identified a number of minor errors and omissions [PD-002].
- 1.1.4 As identified in the Rule 8 Letter [PD-018] and PD-020] section 29 it was identified that updated versions of the Errata should be provided at each deadline, or a "nil return" if not required. Therefore, this shall be a live document throughout the Examination which will be updated at each deadline where necessary.
- 1.1.5 Where a new errata item is identified this will be included in this document and clearly identified when it was added into this Errata Report.
- 1.1.6 The errata are presented in Table 1.1 with the correction provided for clarification.

1.2 Relationship to other documents

- 1.2.1 In addition to this Errata Report, a Place Name Gazetteer [REP3-005] has been produced to address instances where there are local inconsistencies in the terms of place names used in the area of the Project and where similar place names are used in different locations. This highlights to the reader what these are and confirms the place name that the Project is using.
- 1.2.2 This Errata Report should be read alongside the Environmental Statement (ES) Addendum [REP7-154]. The ES Addendum has been prepared to outline updates to the following DCO application documents:
 - a. 6.1 Environmental Statement [APP-138 to APP-155]
 - b. 6.2 Environmental Statement Figures [APP-156 to APP-331]
 - c. 6.3 Environmental Statement Appendices [APP-332 to APP-485]
 - d. 6.4 Environmental Statement Non-Technical Summary (NTS) [APP-486]
- 1.2.3 It is intended that ES Addendum document remains a live document throughout Examination and would be used to track updates and amendments to the Environmental Statement documents, as these are required.

- 1.2.4 The following ES documents are excluded from the ES Addendum:
 - a. Application Document 6.3 Environmental Statement Appendix 2.2 Code of Construction Practice, First Iteration of Environmental Management Plan [REP7-122]
 - Application Document 6.3 Environmental Statement Appendix 2.2 Code of Construction Practice, First Iteration of Environmental Management Plan Annex A Outline Site Waste Management Plan [APP-337]
 - c. Application Document 6.3 Environmental Statement Appendix 2.2 Code of Construction Practice, First iteration of Environmental Management Plan Annex B Outline Materials Handling Plan [REP7-127]
 - d. Application Document 6.3 Environmental Statement Appendix 2.2 Code of Construction Practice, First iteration of Environmental Management Plan Annex C Preliminary Works Environmental Management Plan [REP6-042]
- 1.2.5 Any errata items identified for those documents listed in 1.2.2 above have not been included in this Errata Report. Where items were included in version 1 of the Errata Report [AS-004], these have now been removed and are contained within the ES Addendum [REP7-154].
- 1.2.6 For documents listed in 1.2.4, documents a and d are not included within this Errata Report because they have been updated and submitted as revised documents for Deadline 7. However, documents b and c are included within this Errata Report as they were updated at later deadlines in the Examination timetable.

1.3 Approach to Errata

- 1.3.1 The Applicant is reporting these identified corrections though the following documents:
 - a. an update on the Errata Report [REP6-004] for textual corrections to DCO documents which do not form part of the Environmental Statement.
 - update to the relevant Book of Plans drawing where an error was identified in the drawings. This will make it easier to understand as no interpretation is needed and there will be improved consistency across the Book of Plans.
 - c. document updates For those documents referred to as control documents in the Introduction to the Application [APP-003] these are expected to be updated over the course of the examination following further engagement with the Examining Authority and stakeholders. Any identified minor corrections will be included within the next document update.

Table 1.1 Errata identified within the submission documents

	Table 1.1 Litata identified within the submission documents							
Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.		
APP-047	S51 Dec 2022	Drainage Plans	All Notes/ Volumes	Spelling error	Legend note 2 - replace "Authorise" with "Authorised".	This change was updated in the plans submitted at Deadline 4 [REP4-076, REP4-078, REP4-080].		
APP-151	S51 Dec 2022	Statement of Commonality	Plate 1.1 Table 3.1 Table 4.2	Other – Missing Titles	Missing titles for, Table 3.1, Table 4.2 have been addressed and Plate 1.1 has been removed.	This change was updated in the document submitted at Deadline 1 [REP1-057].		
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 1, Paragraph: 1.2.1	Compound name	Northern Entrance compound - should be "Northern tunnel entrance compound"	This change was updated in the document submitted at Deadline 4 [REP4-136].		
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 2 Paragraph: 1.3.5	Incorrect section numbering	Replace "Chapter 8" with "Section 8"	This change was updated in the document submitted at Deadline 4 [REP4-136].		
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental	Page: 3 Paragraph: 1.3.7	LTC terminology	Replace "north portal" with "North Portal"	This change was updated in the document submitted at Deadline 4 [REP4-136].		

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
		Management Plan - Annex B - Outline Materials Handling Plan				
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 5 Paragraph: 2.1.1	Incorrect section numbering	Replace "Chapter 3" with "Section 3"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 8 Paragraph: 2.3.1, a.	Incorrect section numbering	Replace "Chapter 4" with "Section 4"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 8 Paragraph: 2.3.1, b and c	Incorrect section numbering	Replace "Chapter 6" with "Section 6"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page:14 Paragraph: 3.4.14	Incorrect section numbering	Replace "Chapter 8" with "Section 8"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First	Pages: 15, 16 and 36	LTC terminology	Replace "Main Works Contractors" with "Contractors"	This change was updated in the document submitted

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
		iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Paragraph: 3.5.3, 3.5.7 and 6.3 (first paragraph which in not numbered)			at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 21 Paragraph: 4.3.13	LTC terminology	Replace "OMHP" with "oMHP"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 21 Paragraph: 4.3.14	LTC terminology	Replace "OTMPfCo" with "oTMPfC"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 22 Paragraph: 4.3.16	LTC terminology	Replace "AIL" with "Abnormal Indivisible Loads"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 22 Paragraph: 4.3.17	LTC terminology	Replace "LTC" with "The Project"	This change was updated in the document submitted at Deadline 4 [REP4-136].

Planning Inspectorate Scheme Ref: TR010032 Application Document Ref: TR010032/APP/1.6 DATE: December 2023 DEADLINE: 9 Uncontrolled when printed – Copyright © - 2023 National Highways Limited – all rights reserved

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 23 Paragraph: 4.3.24	Incorrect section numbering	Replace "Chapter 6.2" with "Section 6.2"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 25 Paragraph: 5.4.3	Incorrect section numbering	Replace "Chapter 8" with "Section 8"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 27 Paragraph: 5.4.6 f	Grammatical error	The word "the" should be inserted after the word "around"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 31 Paragraph: 5.4.8 f	LTC terminology	Add the word "compound" after the name "Warley Street"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental	Page: 36 Paragraph: 6.2.15	LTC terminology	Replace the words "Main Works Contractor's" with "Contractor's"	This change was updated in the document submitted at Deadline 4 [REP4-136].

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
		Management Plan - Annex B - Outline Materials Handling Plan				
APP-338	D1	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 41 Paragraph: 7.2.2	Formatting	The properties for the header row in Table 7.1 are incorrectly checked 'Repeat as header row at the top of each page'. The table therefore restarts with the header for 'Section A - Kent Roads' each time the table enters a new page even though that text is referring to a different section of the works.	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 44 Paragraph: 7.3.6	REAC references	At the end of the paragraph add "(REAC Refs LV009, LV011, LV015, LV017, LV021, LV024 and LV026)"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 47 Paragraph: 7.4.16, 7.4.17 and 7.4.18	LTC terminology	Replace "Ockendon Link" with "Ockendon link"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental	Page: 53 Paragraph: 8.1.1	Incorrect section wording	Replace "chapter" with "section"	This change was updated in the document submitted

Planning Inspectorate Scheme Ref: TR010032 Application Document Ref: TR010032/APP/1.6 DATE: December 2023 DEADLINE: 9

Uncontrolled when printed – Copyright © - 2023 National Highways Limited – all rights reserved

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
		Management Plan - Annex B - Outline Materials Handling Plan				at Deadline 4 [<u>REP4-136</u>].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 54 and 55 Paragraph: 8.2.8 and 8.2.13	LTC terminology	Replace "Ockendon Branch railway line" with "London Tilbury Southend railway"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 56 Paragraph: 8.2.22	Incorrect section numbering	Replace "Chapter 4 "with "Section 4"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 57 Paragraph: 8.2.27	Incorrect section numbering	Replace "Chapter 6 "with "Section 6"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 58 Paragraph: 8.2.39	Incorrect section numbering	Replace "Chapter 4 "with "Section 4"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First	Page: 59 Paragraph: 8.4.2	Incorrect section numbering	Replace "Chapter 3 "with "Section 3"	This change was updated in the document submitted

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
		iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan				at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 60 Paragraph: 8.4.4	Incorrect section numbering	Replace "Chapter 6 "with "Section 6"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page: 63 Glossary	Spelling error	Replace "geoglraphical" with "geographical"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Pages: 66 to 70 Annex B.1	Incorrect section wording	Replace "Chapter" with "Section"	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-338	S51 Dec 2022	Environmental Statement Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Pages: 66 to 70 Annex B.1	LTC terminology	Replace "OMHP" with "oMHP"	This change was updated in the document submitted at Deadline 4 [REP4-136].

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9
APP-338	D1	Environmental Statement - Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Page:36 Paragraph: 6.2.17b	Incorrect statement	Text reads "Materially new or materially new adverse environmental effects." Text should read "Materially new or materially different adverse environmental effects."	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-339	D1	Environmental Statement - Appendix 2.2 - Code of Construction Practice, First iteration of Environmental Management Plan - Annex B - Outline Materials Handling Plan	Pages: 18, 54 and 58 Paragraphs: 4.2.5, 8.2.3 and 8.2.38	Incorrect distance	Distance to compound stated as 7km from Hoo Junction rail yard, this is incorrect, it is 4km from Hoo Junction to southern portal tunnel entrance compound and approximately 11km to the A2 compound (due to HGV bans on some roads in Shorne)	This change was updated in the document submitted at Deadline 4 [REP4-136].
APP-487	S51 Dec 2022	Habitats Regulations Assessment Screening Report and Statement to Inform an Appropriate Assessment	Appendix A Figure 24	North view not showing all of noise attenuation measures	North view rescaled to show all noise attenuation measures	Figure updated and found in Appendix A of this document.
APP-487	D1	Habitats Regulations Assessment - Screening Report and Statement to Inform an Appropriate Assessment	Figure 24	Figure missing	Figure is cut off and does not include the full extent of proposed construction noise barriers	Figure updated and found in Appendix A of this document.
APP-495	D3	Planning Statement	Paragraph 5.3.24	Туро	Paragraph says "model provision." Should state "modal provision."	This change was updated in 7.2 Planning Statement

Deleted: No

Deleted:, Document not

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
						submitted at Deadline 9.
APP-495	D1	Planning Statement	Paragraph 6.5.78	Area error	Areas of ancient woodland. Text reads "over the construction phase would include direct loss of 6.43ha of ancient woodland". Text should read "over the construction phase would include the direct loss of 6.92ha of ancient woodland".	This, change was, updated in 7.2 Planning Statement submitted at Deadline 9,
APP-495	D4	Planning Statement	Page: 173 Paragraph: 6.5.216	Incorrect reference to table	Text reads: "Table 6.10 within ES Chapter 6: Cultural Heritage provides a summary of cultural heritage significant effects." Text should read: "Table 6.7 within ES Chapter 6: Cultural Heritage provides a summary of heritage significant effects."	This change was updated in 7.2 Planning Statement submitted at Deadline 9,
APP-495	D1	Planning Statement	Paragraph 7.13.79	Area error	Areas of ancient woodland. Text reads "7.26ha of ancient woodland to the south of the River Thames	This, change was, updated in 7.2, Planning Statement submitted at Deadline 9,

Deleted: 8

Deleted: this time

Deleted: No

Deleted: , Document not

Deleted: this time.

Deleted: No

Deleted: this time

Deleted:, Document not

Deleted: at this time. The correct figures of 5.35ha south and 1.57ha north have been correctly stated elsewhere

Jolotodi the

Deleted: and the judgements on policy compliance made on the basis of those figures.

Application Document	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and	Correction	Commentary for Deadline 9	Deleted: 8
Reference				explanation	and 4.35ha of ancient woodland to the north of the River To compensate for		
					the loss of this woodland, 63.84ha of woodland would be planted".		
					Text should read "5.35ha of ancient woodland to the south of the River Thames and 1.57ha of ancient woodland to the north of the River To compensate for the loss of this woodland, 80.75ha of woodland would be planted".		
APP-495	D4	Planning Statement	Page: 254 Paragraph: 8.7.15	Incorrect wording.	Text reads "establish that the Project benefits very significantly outweigh the benefits". Text should read " establish that the Project benefits very significantly outweigh the disbenefits."	This change was updated in 7.2 Planning Statement submitted at Deadline 9.	Deleted: No Deleted: , Document not Deleted: this time
APP-496	D1	Planning Statement Appendix A – National Policy Statement for National Networks (NPSNN) Accordance Table	Page 97-100 Response to 5.32 NPSNN	Area error	Areas of ancient woodland. Text reads "In total, the Project would result in the	This change was updated in 7.2 Planning Statement	Deleted: No Deleted: , Document not

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
					loss of 6.43ha of ancient woodland" Text should read "In total, the Project would result in the loss of 6.92ha of ancient woodland"	submitted at Deadline 9.
APP-499	D3	Planning Statement Appendix D – Open Space	Pages: 9 and 33-38	Consistency error	Amendment of Orsett Fen area affected by the Project in line with updated information in the Land Registry and the corrected common land boundary (based on DEFRA's Magic Map). The figure was 523,133sqm but should be 523,107sqm.	This change was updated in the document submitted at Deadline 3 [REP3-108].
APP-505	D1	Section 106 Agreement Heads of Terms	Pages: 2, 13, 14 Table: 1.1, 7.5.2, 7.5.4	Incorrect reference	In Table 1.1 and paragraph 7.5.2 delete "New Barn Road, Dartford (between The Beeches and Fairlight Cross)". In paragraph 7.5.4 delete "and New Barn Road".	This change was updated in the document submitted at Deadline 4 [REP4-144].
APP-509	D1	Project Design Report- Part D- General Design South of the River	Pages: 34 and 35 Paragraph: 4.5.17	Incorrect data	Text states "Native species with a broad climate range stretching south have been selected and naturalised	No change, Document to be read alongside, this Errata Report,

Deleted: this time

Deleted: not updated at

Deleted: time

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
					and non-native plants, again with a range that extends into warmer parts of the world, have been selected where appropriate". The following text should be added after this sentence "It is not proposed to use non-native plant species within the AONB."	
APP-517	S51 Dec 2022	Road User Charging Statement	Page: 7 Paragraph: 4.1.1	Incorrect grammar	"and enforcement" should be after "operation"	No change, Document to be read alongside, this Errata Report,
APP-518	D1	Combined Modelling and Appraisal Report	Page: 61 Plate 5.1	Error on plate	Plate shows PCF stage 2 on both sides of image - right side should be PCF stage 3	No change, Document to be read alongside, this Errata Report,
APP-520	D1	Combined Modelling and Appraisal report - Appendix B - Transport Model Package	Page: 3 Plate 2.1	Error on plate	Plate shows PCF stage 2 on both sides of image — right side should be PCF stage 3	No change, Document to be read alongside, this Errata Report,
APP-522	D1	Combined Modelling and Appraisal Report — Appendix C — Transport Forecasting Package	Page: 9 Plate 3.1	Error on plate	Plate shows PCF stage 2 on both sides of image - right side should be PCF stage 3	No change, Document to be read alongside, this Errata Report,
APP-522	D3	Combined Modelling and Appraisal Report — Appendix C	Page:203 Paragraph: 8.2.16	Туро	Text states "forest", should state "forecast."	No change, Document to be read

Deleted: not updated at

Deleted: time

Planning Inspectorate Scheme Ref: TR010032 Application Document Ref: TR010032/APP/1.6 DATE: December 2023 DEADLINE: 9

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9	Deleted: 8
		Transport Forecasting Package				alongside this Errata Report	Deleted: not updated at Deleted: time
APP-526	D1	Combined Modelling and Appraisal Report - Appendix D - Economic Appraisal Package: Economic Appraisal Report	Page: 76 Paragraph: 8.5.6	Content error - minor	Text should state: "The Project's operational, maintenance and renewals emissions total 28,607 tonnes of non-traded emissions and 2,008 tonnes of traded emissions and sum to a total of 30,615 tonnes"	No change, Document to be read alongside this Errata Report.	Deleted: not updated at Deleted: time
APP-526	D1	Combined Modelling and Appraisal Report - Appendix D - Economic Appraisal Package: Economic Appraisal Report	Page: 305 Paragraph: C.1.28	Content error - minor	Text should state that it is a 136 zone system (currently specifies 137).	No change, Document to be read alongside, this Errata Report,	Deleted: not updated at Deleted: time
APP-528	D1	Traffic Forecasts Non-Technical Summary	Pages: 26-36 Plates: 5.10- 5.15	Error on plate	Plate states that they show the link VC values but only if LTC results in a change of flow of between -50 to +50. The mapping shows the VC values for all links.	No change, Document to be read alongside this Errata Report,	Deleted: not updated at Deleted: time
APP-528	D1	Traffic Forecasts Non-Technical Summary	Pages: 19-24 Plates: 5.1-5.6	Legend error	Legend states +101 to +250, should state +51 to +250	No change, Document to be read alongside, this Errata Report,	Deleted: not updated at Deleted: time
APP-528	D3	Traffic Forecasts Non-Technical Summary	Plates: 5.1, 5.2, 5.7, 5.8	Graphical error	The change in flow on Rectory Road (between its junction with School Lane and the A1013) is shown as	No change, Document to be read alongside, this Errata Report,	Deleted: not updated at Deleted: time.¶

leted: not updated at leted: time leted: not updated at leted: time.¶

Application Document Reference	Errata identified at		Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
					being on the northbound carriageway. This should be shown as being on the southbound carriageway.	
APP-528	D3	Traffic Forecasts Non-Technical Summary	Paragraph: 5.2.11 a)	Data error	Text says " up to a maximum of 25% in 2045 in the modelled hours." It should state " up to a maximum of 18% in 2045 in the modelled hours."	No change, Document to be read alongside, this Errata Report,
APP-528	D3	Traffic Forecasts Non-Technical Summary	Plate: 5.5	Graphical error	The increase in flow (in the PM peak) on Warren Road (in Gravesham) is shown as westbound. This should be eastbound.	No change, Document to be read alongside, this Errata Report,
APP-528	D3	Traffic Forecasts Non-Technical Summary	Plates: 5.5 and 5.6	Graphical error	The decrease in flow (in the PM peak) on the A1013 is shown as westbound between Rectory Road and Hornsby Lane. This should be eastbound.	No change, Document to be read alongside, this Errata Report.
APP-529	D1		Pages: Various Plates: 7.2, 7,3, 7,5, 7.6, 7.8, 7.9 and 7.19-7.24 inclusive)	Error on plate	Plate states that they show the link VC values but only if the Project results in a change of flow of between - 50 to +50. The mapping shows the VC values for all links.	This change was updated in the document submitted for Deadline 3 [REP3-112].

Deleted: not updated at

Deleted: time

Deleted: not updated at

Deleted: time

Deleted: 8

Deleted: not updated at Deleted: time.

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9
APP-529	D2	Transport Assessment	Page:124 Plate:7.3	Error on plate	Plate shows DM network but should show DS network.	This change was updated in the documents submitted at Deadline 3 [REP3-122].
APP-529	D3	Transport Assessment	Pages: 173-184 Tables: 7.11, 7.12 and 7.13	Error data	In Table 7.11, for journey time route 28 the eastbound numbers are incorrectly in the westbound columns (and vice versa). In Table 7.12 the times are incorrect from journey time route 11 onwards. In Table 7.13 the DS times reflect the IP times, therefore the journey time change in minutes and as a percentage change are incorrect.	This change was updated in the document submitted for Deadline 3 [REP3-112].
APP-529	D1	Transport Assessment	Plates: 7.10- 7.15 inclusive	Legend error	Legend states +101 to +250, should state +51 to +250.	This change was updated in the document submitted for Deadline 3 [REP3-112].
APP-529	D3	Transport Assessment	Plate: 7.14	Graphical error	The increase in flow (in the PM peak) on Warren Road (in Gravesham) is shown as westbound. This should be eastbound.	This change was updated in the document submitted for Deadline 3 [REP3-112].

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9
APP-529	D3	Transport Assessment	Plates: 7.14 and 7.15	Graphical error	The decrease in flow on the A1013 (in the PM peak) is shown as westbound between Rectory Road and Hornsby Lane. This should be eastbound.	This change was updated in the document submitted for Deadline 3 [REP3-112].
APP-533	D6	Transport Assessment – Appendix D – Scale of Impacts Maps	Pages: 1 and 3 Plates: 1.1 and 1.3	Plate error	On Plate 1.1 the Core interpeak is shown in error rather than the High AM adverse. On Plate 1.3 the core PM adverse is shown rather than the Low AM adverse.	This change was updated in the documents submitted at Deadline 7 [REP7-142]
APP-533	D1	Transport Assessment – Appendix D -Scale of Impacts Maps	Page: 22 Plate 1.22	Incorrect location	The image for 'north' from Plate 1.21 is repeated in Plate 1.22. Plate 1.22 should show the image for the 'south'.	This change was updated in the documents submitted at Deadline 7 [REP7-142]
APP-535	D6	Transport Assessment – Appendix F – Wider Network Impacts Management and Monitoring Policy Compliance	Page: 6 Paragraph: 1.3.8	Incorrect reference	The reference to "Paragraph 5.207 of the NPSNN" is incorrect. The text should be "Paragraph 5.206 of the NPSNN"	No change, Document to be read alongside, this Errata Report,
APP-539	D1	Health and Equalities Impact Assessment	Page:219 Paragraph: 7.11.19	Incorrect data	Text states that 30 residential properties will be subject to demolition. The correct figure is 35. Text states that 26 properties are in locations to the north of	This change was updated in the documents submitted at Deadline 3 [REP3-118]

Deleted: not updated at

Deleted: time

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
					the river. The correct figure is 31.	
APP-541	S51 Dec 2022	Health and Equalities Impact Assessment and Appendix B	HEqIA – Multiple (14 instances) Appendix B – Multiple (4 instances)	Incorrect name use	Use of 'Gammonfields Way Travellers' Site'. It should be 'Gammon Field' Travellers Site (see the Place Name Gazetteer for more detail)	The Place Name Gazetteer [REP3- 005] addresses this erratum.
APP-548	D4	Preliminary Navigational Risk Assessment	Page: 11 Paragraph: 2.2.10	Text error	Text reads: " the Port of Tilbury averaged 3260 two-way vessel movements per annum" Text should read: "the Port of Tilbury handled an average of 3260 vessels (6,520 two-way vessel	This change was updated in the documents submitted at Deadline 5 [REP5-058]
APP-549	S51 Dec 2022	Community Impact Report	Pages: 204 and 206 Paragraph:6.13. 22	Incorrect name use	movements) per annum." Use of 'Gammonfields Way' to describe the location of the travellers' site, rather than using the name in the site (Gammon Field). (See the Place Name Gazetteer for more detail)	The Place Name Gazetteer [REP3- 005] addresses this erratum.
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 1 Paragraph: 1.1.2	Terminology	Replace 'National Policy Statement's' with 'National Policy Statement'	No change, Document to be read alongside, this Errata Report,

Deleted: not updated at

Deleted: time

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 1 Paragraph: 1.1.4	Terminology	Remove 'this Interrelationship Doc'	No change, Document to be read alongside, this Errata Report,
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 1 Paragraph: 1.1.6	Terminology	Remove ' from promoters'	No change, Document to be read alongside, this Errata Report.
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 5 Paragraph: 3.1	LTC Terminology	Should be titled Lower Thames Area	No change, Document to be read alongside, this Errata Report,
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 5 Paragraph: 3.2.3	LTC Terminology	Remove reference to Section 3 - should say Chapter 4	No change, Document to be read alongside, this Errata Report.
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 11 Paragraph: 5.4.2	LTC Terminology	TAG definition - Transport Analysis Guidance	No change, Document to be read alongside, this Errata Report.
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 13 Paragraph: 5.6.3	Туро	Should refer to Chapter 6, not 4	No change, Document to be read alongside, this Errata Report,
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 25 Paragraph: 6.3.11	Туро	Remove reference to LTC	No change, Document to be read alongside this Errata Report

$\overline{}$	
_	
D	eleted: not updated at
D	eleted: time
_	
=	eleted: not updated at
D	eleted: time.
D	eleted: not updated at
D	eleted: time
D	eleted: not updated at
D	eleted: time
D	eleted: not updated at
D	eleted: time
D	eleted: not updated at
D	eleted: time
D	eleted: not updated at
=	eleted: time
_	

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
APP-550	S51 Dec 2022	Interrelationship with other Nationally Significant Infrastructure Projects and Major Development Schemes	Page: 26 Paragraph: 6.4.1	Terminology	Identified 'land' within the freeport, instead of 'areas'	No change, Document to be read alongside, this Errata Report,
APP-553	D1	Benefits and Outcomes Document	Page:24	Incorrect information	Wording states "over £30 million," should state "up to £30 million"	No change, Document to be read alongside, this Errata Report,
AS-040	D1	Additional Submission - 4.1 Statement of Reasons (Clean) (Version 2)	Pages: 60 and 61 Paragraph: 6.3.1 and Table 6.1	Incorrect data	Data shows that the total number of residential properties being demolished is 30. This correct figure is 35.	This change was updated in the document submitted for Deadline 1 [REP1-049].
AS-040	D1	Additional Submission - 4.1 Statement of Reasons (Clean) (Version 2)	Pages: 60-61 Paragraph: 6.3.1 and Table 6.1	Incorrect data	Yellow Stock Mews is counted as one residential property but has been divided into five small units. The update will therefore be 1-5 Yellow Stock Mews.	This change was updated in the document submitted for Deadline 1 [REP1-049].
REP1-022	D3	Special Category Land Plans (Volume C)	Sheet: 35	Update to land classification	Amendment of Orsett Fen area affected by the Project in line with updated information in the Land Registry and the corrected common land boundary (based on DEFRA's Magic Map). Plot 35-65 is incorrect due to differences between	This change was updated in the document submitted for Deadline 3 [REP3-025]

Deleted: not updated at

Deleted: time

Deleted: not updated at

Deleted: time

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
					land ownership and land designation.	
REP1-048	D3	Deadline 1 submission- 4.1 Statement of Reasons	Pages: 68, 69 and 72	Incorrect classification	Amendment of Orsett Fen area affected by the Project in line with updated information in the Land Registry and the corrected common land boundary (based on DEFRA's Magic Map). Removal of 35-65 from the list of plots as this is not classified as Common Land.	This change was updated in the document submitted for Deadline 3 [REP3-081].
REP1-053	D3	Deadline 1 Submission - 4.2 Book of Reference (Clean version)	Pages 3701 and 8344	Incorrect description of land	Amendment of Orsett Fen area affected by the Project in line with updated information in the Land Registry and the corrected common land boundary (based on DEFRA's Magic Map). Text stated "Orsett Fen", this has now been removed.	This change was updated in the document submitted at Deadline 3 [REP3-085].
REP1-053	D3	Deadline 1 Submission - 4.2 Book of Reference (Clean version)	9554	Incorrect classification	Amendment of Orsett Fen area affected by the Project in line with updated information in the Land Registry and the corrected common land boundary (based on DEFRA's Magic	This change was updated in the document submitted for Deadline 3 [REP3-085].

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,	
					Map). Removal of plot 35-65 from Part 5 as this is not classified as Common Land.		
REP1-187	D3	9.15 Localised Traffic Modelling and Appendix A	Section: 3.2 error incorrect. Text reads "3.2, d d 3.2.1, 3.2.2, 3.2.3, 3.2.1, d d 3.2. 2". It should read "3.2, for		This change was updated in the document submitted for Deadline 3 [REP3-126].		
REP1-187	D3	9.15 Localised Traffic Modelling and Appendix A	Page 9, 10 Table 3.1	Numbering error	Against items 3, 4, and 9 the response column referred to paragraph 3.4.9. This should be paragraph 3.5.9 Item 9 also refers to paragraph 3.4.10, this should be 3.5.10.		
REP1-187	D3	9.15 Localised Traffic Modelling and Appendix A	Page 2 Section 2.1	Numbering error	The paragraph numbering of paragraph 2.1.5 is incorrect with two part a's. This has now been corrected to read a, b, c, d.	This change was updated in the document submitted for Deadline 3 [REP3-126].	
REP1-190	D3	9.15 Localised Traffic Modelling Appendix D – Manorway Forecasting Report	Page: 5 Paragraph: 3.3.1	Formatting error	The paragraph and text are not in alignment with the formatting of the document. Paragraph 3.3.1 should read "There are three signalised junctions Table 2.2 respectively."	No change, Document to be read alongside, this Errata Report	

Deleted: not updated at

Deleted: time.¶

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9.
REP2-032	D6	Community Impact Report	Page: 53 Paragraph: 6.2.56	Incorrect text	The paragraph reads: "is the number 695 school bus westbound from the Rochester Grammar School, through Cobham and Sole Street, to Meopham School and then onto ealth Rise." Text should read: "is the number 695 school bus westbound from the Rochester Grammar School, through Cobham and Sole Street, to Meopham School and then onto Istead Rise"	No change, Document to be read alongside, this Errata Report,
REP2-032	D6	Community Impact Report	Page: 53 Paragraph: 6.2.56	Incorrect text	The last sentence of this paragraph should be a separate sub heading titled "Access and recreation."	No change, Document to be read alongside, this Errata Report,
REP2-032	D3	Community Impact Report	Page: 333	Incorrect data	Text states that the Project reduces traffic at Dartford by 21%. The correct figure is 19%.	No change, Document to be read alongside, this Errata Report,
REP3-120	D4	Deadline 3 Submission - Other: 7.14 Outline Traffic Management Plan for Construction v3.0 clean	Table: 4.2	Incorrect data	Text reads: "The section between the A13 and A1013 would be closed for approximately 16 months." Text should read: "The section between the A13	The change was updated in the document submitted at Deadline 4 [REP4-160].

Deleted: not updated at

Deleted: time

Deleted: not updated at

Deleted: not updated at

Deleted: time

Deleted: not updated at

Deleted: time

Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,	Deleted: 8
					and A1013 would be closed for approximately 9 months."	,	
REP4-182	D6	Deadline 4 Submission – 9.86 Post-event submissions, including written submission of	Page: 65 Paragraph:	Incorrect reference	Text reads: "The Applicant refers to paragraph D.6.9 to D.6.23 above".	No change, Document to be read alongside this Errata	Deleted: not updated at
		oral comments, for ISH6	D.7.1		Text should read: "The Applicant refers to paragraph D.5.9 to D.5.23 above."	Report.	Deleted: time
REP4-182	D6	Deadline 4 Submission – 9.86 Post-event submissions, including written submission of oral comments, for ISH6	Page: 65 Paragraph: D.8.1	Incorrect reference	Text reads: "The Applicant refers to paragraph D.6.20 to D.6.23 above."	No change, Document to be read alongside, this Errata Report.	Deleted: not updated at Deleted: time
					Text should read: "The Applicant refers to paragraph D.5.20 to D.5.23 above."		
REP6-089	D8	Deadline 6 Submission – 9.131 Post-event submissions, including written submission of oral comments, for ISH8	Page: 18 Paragraph: 4.1.8	Incorrect reference to Planning Act 2008	Text reads: "AT noted that the position just espoused was made without prejudice to AT's broader submission, that the related housing development does not limit it to the definitions in the Planning Act 2008."	No change, Document to be read alongside, this Errata Report,	Deleted: not updated at Deleted: time
					Text should read: "AT noted that the position just		

Planning Inspectorate Scheme Ref: TR010032 Application Document Ref: TR010032/APP/1.6 DATE: December 2023 DEADLINE: 9 espoused was made without


Application Document Reference	Errata identified at	Document Name	Section (page, paragraph)	Nature of Erratum and explanation	Correction	Commentary for Deadline 9,
					prejudice to AT's broader submission, that the related housing development does not limit it to the definitions in the Town and Country Planning Act 1990."	
REP6-111	D8	Deadline 6 Submission – 9.152 Responses to the Examining Authority's ExQ2 Appendix E – 9 Noise & Vibration	Page: 12 and 14	Incorrect reference to time period	Text reads "Commitment to undertake no earthworks activities within 300 metres of any sensitive receptors during daytime and evening periods." Text should read "Commitment to undertake no earthworks activities within 300 metres of any sensitive receptors during evening or overnight periods."	No change, Document to be read alongside, this Errata Report, This is an isolated drafting error which is correct elsewhere in [REP6- 111].

Deleted: not updated at

Deleted: time.

Appendices

Appendix A HRA Figure 24



If you need help accessing this or any other National Highways information, please call 0300 123 5000 and we will help you.

visit www.nationalarchives.gov.uk/doc/open-government-licence/

write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or email psi@nationalarchives.gsi.gov.uk.

If you have any enquiries about this publication email info@nationalhighways.co.uk
or call 0300 123 5000°.

*Calls to 03 numbers cost no more than a national rate call to an 01 or 02 number and must count towards any inclusive minutes in the same way as 01 and 02 calls.