

Clyde & Co LLP
The St Botolph Building
138 Houndsditch
London
EC3A 7AR
United Kingdom

Telephone: +44 (0) 20 7876 5000 Facsimile: +44 (0) 20 7876 5111 DX: 160030 Lime Street 5

Ms Robbins
The Planning Inspectorate
National Infrastructure
C Eagle Wing
Temple Quay House
2 The Square
Temple Quay
Bristol
BS1 6PN

Attn Lily Robbins

Our Ref Your Ref Date

10276966 TR030007 27 September 2023

Dear Ms Robbins

Immingham Eastern Ro-Ro Terminal (TR030007)

We write on behalf of the Applicant, Associated British Ports, in respect of the above.

It has come to the Applicant's attention that there is a disparity in the currents shown in the overview images (simulation track plots) and the model data for 7 runs in the following documents:

- [APP-089] 8.4.10(b) Environmental Statement Volume 3 Appendix10.2 Navigation Simulation Study - Part 1;
- **[APP-090]** 8.4.10(b) Environmental Statement Volume 3 Appendix 10.2 Navigation Simulation Study Part 2; and
- [APP-091] 8.4.10(c) Environmental Statement Volume 3 Appendix 10.3 Navigational Simulation - Stakeholder Demonstrations.

The identified runs are runs 18, 24, 53,54 and 55 in **[APP-089 – APP-090]** and runs 26 and 29 in **[APP-091]**. The flow direction in the detailed graphs, which form part of the plots, have also been clarified. All flow directions now refer to the direction in which the current is flowing (to).

Accordingly, the Applicant has updated the documents – as a new version 2 of each document – which can be found here:

The Applicant would be most grateful if these could be placed before the Examining Authority and accepted into the Examination.

If you have any questions arising from the information above, please do not hesitate to contact us at ________.

10276966 127318674.1

CLYDE&CO

Yours sincerely

Brian Greenwood

Brian Greenwood Clyde & Co LLP

10276966 127318674.1