From:

To: East Anglia ONE North; East Anglia Two
Subject: D 10 submission video recordings

**Date:** 06 May 2021 20:21:04

Attachments: Video.MOV

Video 1.MOV Video 2.MOV

## RICHARD REEVES AP EI1N AFP 133 / IP 2002765

Please see attached video recordings showing the scale of soil sampling, trial pits, and borehole drilling currently on-going on the borders of

Boring to a depth of over 30m has been referenced by the Applicant - boring through the aquifer previously described as fragile and vulnerable is now described as routine. The large diggers pictured are the ones that have been the subject of complaint by IPs for distressing vulnerable livestock.

Although a consultant archaeologist was reported to be present, mostly sitting in a car, the buckets of the extremely large excavators were digging straight down to 4.5 m, dumping all soils and till in one giant pile. The operatives took samples from this pile, put them in plastic bags, then the excavator simply dragged the entire spoil heap back into the hole and tamped it down. Can anyone explain please how any extant archaeological features that may be present could possibly survive this process?

It must also be noted please that I have previously provided photo evidence of unexplored historic ordnance found in plot 12, the track there having been a tank track in frequent use in WW2. Has any independent survey or search for further unexploded ordnance been completed prior to current excavations.

With reference to the videos, there is commentary included on the sound track of each, but all were recorded during current works in plots 4, 11, and bordering 10 and

I would like to reserve the opportunity to comment further on these issues and provide further evidence of inadequate procedure on the part of the applicant at Deadline 11, and request to attend the next ISH as a resident AP / IP.

Many thanks as always for reviewing this material.