

Further to the comments made at the last open hearing with respect to repeated flooding throughout the numerous panel areas. In order to further support these comments and following the first period of winter rain the same pattern of flooding has been experienced once again. The uploaded pdf entitled October 24 is a brief overview of some of the areas affected and their associated panel area references. The group has further video evidence showing much more detail unfortunately the site does not accept uploads of this type.

These examples of regular flooding will only be made worse during installation and throughout the operational phase of the development. They are regular and repeatable as demonstrated by the photographs submitted previously and those attached to this submission



A) Mill lane taken 09/10/2024. Entrance to the proposed Carpark. Looking SW. Panel Area F



B) Mill lane taken 09/10/2024. Entrance to the proposed Carpark. Looking NE Panel Area F



C) Mount pleasant Farm entrance to Substation taken 09/10/2024. Panel Area C



D) Mount pleasant Farm entrance to Substation taken 09/10/2024. Panel Area C



E & F Leaving Bishopton Towards Redmarshall & Entering Bishopton from SE taken 09/10/2024. Panel areas E & F

