# Southampton to London Pipeline Project

Scoping Report Volume 2: Appendices Figures

PINS Reference Number EN070005 July 2018



#### **Scoping Report**

#### **Contents of Scoping Report**

**Digital file 1 – Scoping Report Volume 1 – Chapters and Appendices** 

Digital file 2 – Scoping Report Volume 2 – Figures Chapters 1 – 7

Digital file 3 – Scoping Report Volume 2 – Figures Chapters 8 – 9

Digital file 4 – Scoping Report Volume 2 – Figures Chapter 10

Digital file 5 – Scoping Report Volume 2 – Figures Chapter 11

Digital file 6 – Scoping Report Volume 2 – Figures Chapters 13 – 16

Digital file 7 – Scoping Report Volume 2 – Figures Appendices



### Volume 2: Appendix Figures

#### **Volume 2: Appendix Figures**

### **List of Figures**

A3.	Appendix 3 – Scoping Survey Methodology Report
A3.1	Indicative Botany Survey Areas
A3.2	Indicative Reptile Survey Areas
A3.3	Ground Investigation Borehold Locations
A4.	Appendix 4 – Habitat Regulations Assessment Screening
A4.1	HRA Screening Report Overview
A4.2	HRA Screening Report Littleton Lane Reservoirs
A4.3	HRA Screening Report Bourley and Long Valley SSSI
A4.4	HRA Screening Report Colony Bog and Bagshot Heath SSSI
A4.5	HRA Screening Report Chobham Common SSSI
A4.6	HRA Screening Report Eelmoor Marsh SSSI
A4.7	HRA Screening Report Suitable Alternative Natural Greenspaces
A4.8	HRA Screening Report Bourley and Long Valley SSSI Dartford Warblers
A4.9	HRA Screening Report Bourley and Long Valley SSSI Nightjar
A4.10	HRA Screening Report Bourley and Long Valley SSSI Woodlark
A4.11	HRA Screening Report Chobham Common SSSI Dartford Warblers
A4.12	HRA Screening Report Chobham Common SSSI Nightjar
A4.13	HRA Screening Report Chobham Common SSSI Woodlark
A4.14	HRA Screening Report Colony Bog and Bagshot Heath SSSI Dartford Warblers
A4.15	HRA Screening Report Colony Bog and Bagshot Heath SSSI Nightjar
A4.16	HRA Screening Report Colony Bog and Bagshot Heath SSSI Woodlark
A4.17	HRA Screening Report Eelmoor Marsh SSSI Dartford Warblers
A4.18	HRA Screening Report Eelmoor Marsh SSSI Nightjar
A4.19	HRA Screening Report Eelmoor Marsh SSSI Woodlark
A5.1	Appendix 5.1 – Water Framework Directive Screening and Scopping Assessment
A5.1.1	Water Framework Directive Surface Water Bodies
A5.1.2	Water Framework Directive Groundwater Bodies
A5.2	Appendix 5.2 – Flood Risk Data
A5.2	Flood Risk Sources
A8.2.	Appendix 8.2 – Traffic and Transportation
	Section A DFT Traffic Flows Within 2km of the Proposed Pipeline
A8.2.2	Section H DFT Traffic Flows Within 2km of the Proposed Pipeline
A8.2.3	Section A Collision Clusters Within 2km of the Proposed Pipeline
A8.2.4	Section H Collision Clusters Within 2km of the Proposed Pipeline





## Appendix 3


Figures


Scoping Report Volume 2































































































































## Appendix 4


Figures


Scoping Report Volume 2


























































## Appendix 5.1

Figures

Scoping Report Volume 2









## Appendix 5.2


Figures


Scoping Report Volume 2









































## Appendix 8.2

Figures

Scoping Report Volume 2



