


Reproduced from Ordnance Survey Digital Data with the sanction of the Controller of HM Stationery Office. Crown Copyright Reserved.



- Previously identified archaeological features:  
(from report on cropmarks by Air Photo Services, 2003)
- ditch
  - possible ditch
  - ridge and furrow
  - natural frost crack
  - bank
  - limit of evaluation area
  - shallow soil
  - deep soil




Figure 5.2

Figure 5.1

Figure 5.4

A14 Improvement  
Ellington to Fen Ditton  
Geophysical Surveys of Areas GP1 to GP7  
November 2008

Figure 5.3: Survey data (Area GP5 + survey by Pre-Construct Geophysics) with aerial photography interpretation and services

0 1:5000 200m