

Reproduced from Ordnance Survey Digital Data with the sanction of the Controller of HM Stationery Office. Crown Copyright Reserved.

- Previously identified archaeological features:
(from report on cropmarks by Air Photo Services, 2003)
- ditch
 - possible ditch
 - ridge and furrow
 - natural frost crack
 - bank
 - limit of evaluation area
 - shallow soil
 - deep soil

**A14 Improvement
Ellington to Fen Ditton**
Geophysical Surveys of Proposed Reservoir
Locations: April 2009


Figure R1.3: Survey data: Site R1 (Brampton)
+ survey by Pre-Construct Geophysics, with
aerial photography interpretation
and selected services

0 1:5000 200m

Figure R1.4

Figure R1.1

Figure R1.2



Brampton Wood
Surveyed by Bartlett - Clark Consultancy (01865 200864)
for Cambridge Archaeological Unit