




BRAMPTON LODGE  
Brampton, Cambridgeshire  
Geophysical Survey 2009  
Figure 17: Summary of findings (I)



- magnetic anomalies (archaeological ?)
- magnetic anomalies (natural / non-archaeological ?)
- strong (recent ?) magnetic disturbances
- strong individual magnetic anomalies
- linear magnetic anomalies (cultivation ?)
- pipe

- approximate limit of evaluation area
- A14 improvement: proposed route