

Appendix 4 - Photomontage Junction 1 M54 roundabout

Example photographs illustrating some of the areas which have been incorrectly identified by the applicant as established woodland lost to the scheme.

A) South of junction M54 / A460 looking north



Area of verge and pavement included in Woodland Lost

B) Junction 1 of M54 west-bound slip road looking west



Area of verge included in Woodland Lost areas

C) End of M54 Junction 1 west-bound exit slip road looking east



Area of scrub included as established woodland area lost

D) M54 Junction 1 east-bound slip road looking east



Area of verge and pavement included in Woodland Lost

E) End of M54 Junction 1 east-bound exit slip road looking north-east



Area of verge and pavement included in Woodland Lost

F) North of junction M54 / A460 looking south east



Area of verge and pavement included in Woodland Lost